

# ISO/TR 10064-6:2009-02 (E)

## Code of inspection practice - Part 6: Bevel gear measurement methods

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions and symbols .....</b>	<b>2</b>
<b>3.1</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>3.2</b>	<b>Symbols .....</b>	<b>3</b>
<b>4</b>	<b>Bevel gear measurement .....</b>	<b>4</b>
<b>4.1</b>	<b>Manufacturing and purchasing considerations .....</b>	<b>4</b>
<b>4.2</b>	<b>Manufacturing documentation .....</b>	<b>5</b>
<b>4.3</b>	<b>Process control .....</b>	<b>5</b>
<b>4.4</b>	<b>Measurement methods .....</b>	<b>5</b>
<b>4.5</b>	<b>Additional considerations .....</b>	<b>6</b>
<b>4.6</b>	<b>Acceptance criteria .....</b>	<b>7</b>
<b>5</b>	<b>Measuring methods and practices .....</b>	<b>7</b>
<b>5.1</b>	<b>Guidelines for measurement of gear characteristics .....</b>	<b>7</b>
<b>5.2</b>	<b>Measuring practices .....</b>	<b>8</b>
<b>5.3</b>	<b>Measurement of pitch deviations .....</b>	<b>10</b>
<b>5.4</b>	<b>Measurement of bevel gear runout .....</b>	<b>16</b>
<b>5.5</b>	<b>Flank form measurement .....</b>	<b>18</b>
<b>5.6</b>	<b>Contact pattern checking .....</b>	<b>25</b>
<b>5.7</b>	<b>Single-flank composite inspection .....</b>	<b>30</b>
<b>5.8</b>	<b>Double-flank composite testing .....</b>	<b>30</b>
<b>5.9</b>	<b>Tooth thickness measurement .....</b>	<b>33</b>
<b>5.10</b>	<b>Manufacturing applications .....</b>	<b>36</b>
<b>6</b>	<b>Recommended datum surface tolerances .....</b>	<b>36</b>
<b>Bibliography .....</b>		<b>37</b>