

DIN EN 13042-3:2010-05 (E)

Machines and plants for the manufacture, treatment and processing of hollow glass - Safety requirements - Part 3: IS machines (includes Amendment A1:2009)

Contents	Page
Foreword	3
Introduction	4
1 Scope	5
2 Normative references	6
3 Terms and definitions	7
4 List of significant hazards	7
5 Safety requirements and/or protective measures	9
5.1 General	9
5.2 Starting and stopping and unexpected start-up	10
5.3 Emergency-stop equipment	10
5.4 Prevention of unexpected movements of individual mechanisms	10
5.5 Walking surfaces	11
5.6 Operation of manual controls	11
5.7 Removal of broken glass	11
5.8 Noise	11
5.9 Guards	12
5.10 Heat-protective equipment	12
5.11 Gob distributor and interceptor	12
5.12 Gob distributor operation	12
5.13 Necessary movements in case of power failure	13
5.14 Electrical equipment	13
5.15 Pneumatic system	13
5.16 Energy supply disconnecting devices	13
6 Verification of safety requirements and/or protective measures	13
7 Information for use	14
7.1 General	14
7.2 Accompanying documents (in particular: instruction handbook)	14
7.3 Marking	15
Annex A (informative) Glossary	16
Annex B (informative) Blow and blow process	17
Annex C (informative) Press and blow process	18
Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC	19
Annex ZB (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC"	20
Bibliography	21

Tables Table 1 -- List of significant hazards	8
Table 2 -- Individual testing for requirements stated in Clause 5	13