

DIN EN 13112:2011-03 (E)

Tannery machines - Splitting and bandknife shearing machines - Safety requirements (includes Amendment A1:2009)

Contents	Page
Foreword.....	4
Introduction	5
1 Scope	5
2 Normative references	5
3 Terms and definitions - Terminology.....	8
4 A1 List of significant hazards A1	10
4.1 Mechanical hazards	11
4.1.1 Splitting machine	11
4.1.2 Bandknife shearing machine	12
4.2 Electrical hazard	13
4.3 Slip trip and fall hazard	13
4.4 High pressure fluid ejection	13
4.5 Dust and fire	13
4.6 Noise	13
4.7 Bandknife changing.....	13
5 Safety requirements and/or measures	14
5.1 General.....	14
5.2 Common requirements concerning splitting machines	14
5.2.1 Mechanical equipment	14
5.2.2 Electrical equipment.....	15
5.2.3 Slip, trip and fall hazard	15
5.2.4 High pressure fluid ejection	15
5.2.5 Dust and fire prevention	16
5.2.6 Noise	16
5.2.7 Control system.....	16
5.2.8 Emergency stop equipment.....	17
5.2.9 Bandknife changing.....	17
5.3 Requirements concerning hazards in the working zone	18
5.3.1 Splitting machine	18
5.3.2 Bandknife shearing machine	19
5.4 Requirements concerning hazards in the accessible zone	20
5.4.1 Splitting and bandknife shearing machine	20
5.4.2 Bandknife shearing machine	20
6 Verification of the safety requirements and/or measures	20
7 Information for use	26
7.1 A1 General	26
7.2 Signal and warning devices A1	26
7.3 Instruction Handbook.....	26
7.3.1 Machine.....	26
7.3.2 Installation of the machine	27
7.3.3 Transportation and Storage of the machine and machine parts	27
7.3.4 Use of the machine	27
7.3.5 Maintenance	28
7.4 Marking	28
Annex A (normative) Dust and fire prevention	35
A.1 Splitting machine	35

A.2	Bandknife shearing machine	35
Annex ZA (informative)	Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC	36
Annex ZB (informative)	Relationship between this European Standard and the Essential Requirements of EU Directive 2006/42/EC	37
Bibliography	38