

# DIN 743-2:2012-12 (E)

## Calculation of load capacity of shafts and axles - Part 2: Theoretical stress concentration factors and fatigue notch factors

---

<b>Contents</b>		<b>Page</b>
1	Scope .....	5
2	Normative references .....	5
3	Symbols, designations and units.....	5
4	Fatigue notch factor .....	6
4.1	Definition of fatigue notch factor .....	6
4.2	Experimentally determined fatigue notch factors .....	6
4.2.1	Parallel keyway and interference fit.....	6
4.2.2	Fatigue notch factors for splined shafts, serrated shafts and involute spline shafts.....	8
4.2.3	Fatigue notch factors for round bars with V-notch.....	10
4.2.4	Fatigue notch factors for circumferential rectangular notch.....	11
4.3	Fatigue notch factors for notches with known stress concentration factor .....	12
4.3.1	Shoulder, U-notch, shoulder with undercut, transverse hole .....	12
4.3.2	Notch cases not yet dealt with .....	14
5	Stress concentration factors .....	14
5.1	Definition of stress concentration factor .....	14
5.2	Stress concentration factors for different notch shapes .....	15
5.2.1	Shoulder and U-notch .....	15
5.2.2	Shoulder with undercut.....	22
5.2.3	Transverse hole .....	23
6	Size influence factors .....	24
6.1	General information.....	24
6.2	Technological size influence factor $K_1(d_{\text{eff}})$ .....	24
6.3	Geometrical size influence factor $K_2(d)$ .....	26
6.4	Geometrical size influence factor $K_3(d)$ .....	27
7	Influence factor for surface roughness $K_{F\sigma,\tau}$ .....	28
8	Influence factor for surface conditioning $K_V$ .....	30
Bibliography .....		34

### Figures

Figure 1— Fatigue notch factors for splined shafts, serrated shafts and involute spline shafts .....	8
Figure 2 — Fatigue notch factors for round bars with circumferential V-notch [2].....	10
Figure 3 — Circumferential rectangular notch for circlips according to DIN 471 and structural radius $\rho^*$ according to Neuber [9] .....	11
Figure 4 — Sensitivity factor $n$ .....	13
Figure 5 — Stress concentration factors for notched round bars in tension .....	16
Figure 6 — Stress concentration factors for notched round bars in bending .....	17
Figure 7 — Stress concentration factors for notched round bars in torsion .....	18
Figure 8 — Stress concentration factors for shouldered round bars in tension.....	19
Figure 9 — Stress concentration factors for shouldered round bars in bending.....	20
Figure 10 — Stress concentration factors for shouldered round bars in torsion .....	21

<b>Figure 11 — Shoulder with undercut.....</b>	<b>22</b>
<b>Figure 12 — Stress concentration factors for round bars with transverse hole in tension/ compression, bending or torsion (tension/compression [2], bending and torsion [1]) .....</b>	<b>23</b>
<b>Figure 13 — Technological size influence factor <math>K_1(d_{\text{eff}})</math> .....</b>	<b>25</b>
<b>Figure 14 — Geometrical size influence factor <math>K_2(d)</math> .....</b>	<b>26</b>
<b>Figure 15 — Geometrical size influence factor <math>K_3(d)</math> .....</b>	<b>27</b>
<b>Figure 16 — Influence factor for surface roughness <math>K_{FO}</math>.....</b>	<b>29</b>
<b>Figure 17 — Influence factor for surface conditioning, <math>K_V</math>, in chemico-thermal processes .....</b>	<b>31</b>
<b>Figure 18 — Influence factor for surface conditioning, <math>K_V</math>, in mechanical processes .....</b>	<b>32</b>
<b>Figure 19 — Influence factor for surface conditioning, <math>K_V</math>, in thermal processes .....</b>	<b>32</b>
<b>Tables</b>	
<b>Table 1 — Fatigue notch factors <math>\beta_{\sigma,\tau}(d_{BK})</math> for shaft-hub connections .....</b>	<b>7</b>
<b>Table 2 — Relative stress gradient <math>G'</math>.....</b>	<b>14</b>
<b>Table 3 — Stress concentration factor constants <math>A, B, C</math> and exponent <math>z</math>.....</b>	<b>15</b>
<b>Table 4 — Influence factor for surface conditioning, <math>K_V</math>, as a function of the technological process; guidance values .....</b>	<b>33</b>