

# ISO/TS 8000-311:2012-04 (E)

## Data quality — Part 311: Guidance for the application of product data quality for shape (PDQ-S)

---

Contents	page
1. Scope .....	1
2. Normative references .....	2
3. Terms, definitions and abbreviated terms .....	3
3.1 Terms and definitions .....	3
3.1.1 application .....	3
3.1.2 application protocol .....	3
3.1.3 application reference model .....	3
3.1.4 data exchange .....	3
3.1.5 product .....	3
3.1.6 product data .....	3
3.1.7 accuracy .....	4
3.1.8 inspection result .....	4
3.1.9 measurement requirement .....	4
3.1.10 product data quality .....	4
3.1.11 product shape data .....	4
3.1.12 quality criterion .....	4
3.1.13 threshold .....	5
3.1.14 inspection .....	5
3.1.15 quality .....	5
3.1.16 quality requirement .....	5
3.2 Abbreviated terms .....	5
4. Overview of PDQ-S .....	6
4.1 Purpose, approach and expected usage scenarios .....	6
4.2 Structure of ISO 10303-59 .....	6
4.3 PDQ-S schema structure .....	7
4.4 Target shape model .....	8
4.5 Relationship between ISO 10303-59 and other International Standards dealing with nominal representation of product data .....	8
4.6 Major characteristics of PDQ-S .....	10
4.6.1 Quality criteria of three dimensional shape data .....	10
4.6.2 Enabler of better association between PDQ checking systems and healing systems .....	10
4.6.3 Standardization of the external specifications of quality checking algorithms .....	11
4.6.4 Optimization of data quality check environment by the user .....	11
4.6.5 Extensibility to non-shape product data quality problems .....	12
5. Considerations for facilitating the use of PDQ-S .....	13
5.1 General .....	13
5.2 Relationship between product data quality problems and quality criteria .....	13
5.2.1 Types of product data quality problem .....	13
5.2.2 B-rep is not appropriate (erroneous_data) .....	13
5.2.3 Accuracy of B-rep is not satisfactory .....	13
5.2.4 Shape manipulation process by CAX systems fails .....	15
5.3 Examples of selecting data quality criteria for practical engineering purposes .....	17
5.3.1 Overview of the example scenarios .....	17
5.3.2 A scenario of product data exchange during digital assembly .....	17
5.3.3 A scenario of product data exchange during collaborative product development by an	

assembly manufacturer and parts suppliers .....	18
5.3.4 A scenario of product data exchange during production equipment/die development aiming at machining dies.....	18
5.4 Recommended procedure for promoting PDQ-S .....	20
6. Ensuring conformance with PDQ-S .....	22
6.1 General.....	22
6.2 Underlying concepts of PDQ-S .....	22
6.2.1 Usage scenarios of PDQ-S .....	22
6.2.2 Relationship between a product data and its data quality information.....	23
6.3 Two methods of using PDQ-S .....	25
6.4 Modifying existing APs in order to make them PDQ-S conformant.....	26
6.4.1 General .....	26
6.4.2 Extension of an existing AP with PDQ-S modules .....	26
6.4.3 PDQ-S modules.....	26
6.4.4 Proposed procedure for creating a PDQ-S conformant AP.....	27
Annex A (normative) Information object registration.....	29
A.1 Document identification.....	29
Annex B (informative) Technical discussion .....	30
B.1 Background .....	30
B.2 Definition of product data quality .....	30
Annex C (informative) Comparison of ISO 10303-59 and ISO/PAS 26183 .....	32
C.1 Similarity.....	32
C.2 Difference.....	32
C.1.1 Representation method .....	32
C.1.2 Target industry.....	32
C.1.3 Target data type .....	32
Annex D (informative) Instantiation examples .....	33
D.1 General.....	33
D.2 Graphical notation for instances .....	33
D.3 Instances for short_length_edge .....	34
D.4 Instances for gap_between_edge_and_base_surface .....	55
Bibliography.....	59
Index.....	61
Figures	
Figure 1 — Structure of PDQ-S schemas.....	8
Figure 2 — Schema level diagram of relationships between PDQ-S schemas (inside the box) and other resource schemas .....	9
Figure 3 — Dragging a self-intersecting string into a line.....	16
Figure 4 — Relation between product data quality information in PDQ-S and product model data ...	24
Figure 5 — An approach to modifying existing APs in order to make them PDQ-S conformant .....	25
Figure 6 — Conceptual scheme of extension of AP using PDQ-S module.....	27
Figure B. 1 — Quality of product, product model and product data.....	31
Figure D.1 — Example usage of the notation .....	34
Figure D.2 — A typical example of short length edge .....	35
Figure D.3 — Example instances of quality information for use in requirement or declaration of short_length_edge without specified accuracy (1 of 3).....	36
Figure D.4 — Example instances of quality information for use in requirement or declaration of short_length_edge without specified accuracy (2 of 3).....	37

Figure D.5 — Example instances of quality information for use in requirement or declaration of short\_length\_edge without specified accuracy (3 of 3) ..... 38

Figure D.6 — Example instances of quality information for use in the improvement of quality of short\_length\_edge (1 of 8) ..... 44

Figure D.7 — Example instances of quality information for use in the improvement of quality of short\_length\_edge (2 of 8)..... 45

Figure D.8 — Example instances of quality information for use in the improvement of quality of short\_length\_edge (3 of 8)..... 46

Figure D.9 — Example instances of quality information for use in the improvement of quality of short\_length\_edge (4 of 8)..... 47

Figure D.10 — Example instances of quality information for use in the improvement of quality of short\_length\_edge (5 of 8)..... 48

Figure D.11 — Example instances of quality information for use in the improvement of quality of short\_length\_edge (6 of 8)..... 49

Figure D.12 — Example instances of quality information for use in the improvement of quality of short\_length\_edge (7 of 8)..... 50

Figure D.13 — Example instances of quality information for use in the improvement of quality of short\_length\_edge (8 of 8)..... 51