

# ISO 13577-4:2014-09 (E)

## Industrial furnace and associated processing equipment - Safety - Part 4: Protective systems

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 <b>Scope</b> .....		1
2 <b>Normative references</b> .....		1
3 <b>Terms and definitions</b> .....		1
4 <b>Design requirements for equipment in a protective system</b> .....		4
4.1 <b>General</b> .....		4
4.2 <b>Requirements for protective systems</b> .....		5
4.3 <b>Fault assessment for the hardwired section of protective systems</b> .....		15
4.4 <b>Failure of utilities</b> .....		15
4.5 <b>Reset</b> .....		15
<b>Annex A (informative) Explanation of techniques and measures for avoiding systematic faults</b> .....		16
<b>Annex B (informative) Examples of techniques for avoiding failures from external wiring</b> .....		18
<b>Annex C (informative) Examples for the determination of safety integrity level SIL using the risk graph method</b> .....		22
<b>Annex D (informative) Example of an extended risk assessment for one safety instrumented function using the IEC 61511 method</b> .....		39
<b>Annex E (informative) Sample schematic diagrams of protective system</b> .....		46
<b>Annex F (normative) Hardwiring protective systems</b> .....		61
<b>Bibliography</b> .....		71