

ISO 16891:2016-01 (E)

Test methods for evaluating degradation of characteristics of cleanable filter media

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms	4
5	Principle	5
6	Test specimen, equipment and test procedure	6
6.1	General	6
6.2	Preparation of sheets for gas exposure	7
6.2.1	Shape and size of tensile specimen	7
6.2.2	Sample sheet for exposure	7
6.2.3	Selection of sample sheet through air permeability measurement	8
6.2.4	Filter media for exposure	8
6.3	Sample preparation	9
6.3.1	Exposure system	9
6.3.2	Heating system	11
6.3.3	Test gas supply system	11
6.3.4	Gas analyzer	11
6.3.5	Gas treatment device	12
6.4	Exposure conditions and procedures	12
6.4.1	Exposure conditions	12
6.4.2	Exposure period and number of exposure	12
6.4.3	Attachment of filter sample sheets in the sample case	13
6.4.4	Implementation of the exposure	13
7	Tensile strength measurement of exposed specimen	14
7.1	Tensile test device	14
7.2	Preparation of a tensile test specimen	14
7.3	Method of tensile test	14
7.4	Characterization of the degradation	15
8	Test report	16
Annex A (informative) Causes and results of degradation of fabrics		17
Annex B (informative) Possible evaluation method for characteristic change of fabrics		18
Annex C (informative) Theoretical consideration of degradation mechanism		19
Annex D (informative) Determination of specimen size		22
Annex E (informative) Experimental setup for gas exposure		26
Annex F (informative) Service temperature of filter materials		30

Annex G (informative) Examples of measured data of fabric at different circumstances	31
Annex H (informative) Example of test report	37
Bibliography	41