

ISO/TR 10064-1:2017-07 (E)

Code of inspection practice - Part 1: Measurement of cylindrical gear tooth flanks

Contents		Page
Foreword		vi
1	Scope	1
2	Normative references	1
3	Terms, definitions, symbols and abbreviated terms	1
4	General considerations	5
4.1	Background	5
4.2	Required inspection information	5
4.3	Measurement selection	5
4.3.1	Substitution of measurement methods	5
4.3.2	First piece inspection	5
4.3.3	Sampling and statistical process control	5
5	Conventions and measurement positions	6
5.1	General	6
5.2	Datum axis	6
5.3	Left or right flank	6
5.4	Left hand or right hand helical gears	7
5.5	Numbering of teeth and flanks	7
5.6	Numbering of pitches	8
5.7	Number of pitches "k" in a deviation symbol subscript	8
6	Types of measuring equipment and principle	8
6.1	General	8
6.2	Measurement methods	14
6.2.1	Generative measurement methods	14
6.2.2	Non-generative measurement methods	16
6.2.3	Pitch measurement methods	17
6.2.4	Hand-held pitch measuring devices	18
6.2.5	Radial runout measurement	20
6.2.6	Computer tomography methods for small gears	21
6.2.7	Optical devices for small spur gears	21
6.3	Calibration of equipment	22
6.4	Tooth thickness, differences between CNC/CMM and manual measurement	22
6.5	"In-process" gear measurement on manufacturing machines	23
6.6	Gear mounting	23
6.7	Example output format from a CNC GMM	24
6.7.1	General	24
6.7.2	Example evaluations of modified helices and profiles	27
7	Recommended measurement procedure and good measurement practice	28
7.1	Measurement procedure	28
7.2	Probe problems when measuring aluminium parts	30
7.3	Suitable artefacts for calibration of measuring machines	30
8	Inspection procedures for gears that are too large for gear inspection machines	31
8.1	General	31
8.2	Profile inspection using portable device	31
8.2.1	Disassembly of segments	31

8.2.2	Measurement by portable gear inspection device using coordinates	31
8.2.3	Profile inspection by gear tooth caliper	32
8.3	Inspection of helix form deviation	36
8.3.1	Inspection of helix form deviation on the gear cutting machine	36
8.3.2	Straightness inspection using a cylinder	37
8.3.3	Inspection of the tooth contact pattern	37
8.4	Inspection of the pitch	38
8.4.1	Calculation of pitch	38
8.4.2	Inspection using an automatic device on the cutting machine: inspection of the single circular pitch and the cumulative pitch deviation	38
8.4.3	Manual inspection: inspection of base pitch, pb, and base pitch deviations, fpb	39
8.5	Measuring tooth thickness	39
8.6	Measuring gear radial runout and axial runout of reference surfaces	39
9	Measurement analysis -- Profile, helix, pitch and radial runout	39
9.1	Profile	39
9.1.1	Profile deviation	39
9.1.2	Profile deviation diagram	40
9.1.3	Evaluation of profile diagrams	41
9.1.4	Algebraic signs of fH, fb and f	42
9.1.5	Mean profile slope deviation, fHm	42
9.2	Helix	43
9.2.1	General	43
9.2.2	Helix deviation diagram	44
9.2.3	Evaluation of helix diagrams	45
9.2.4	Algebraic signs of fH and f	46
9.2.5	Machine corrections based on mean helix slope deviation, fHm	47
9.3	Pitch	48
9.3.1	Pitch deviation	48
9.3.2	Pitch deviation measurement	48
9.3.3	Relationships of pitch parameters and measuring methods	48
9.3.4	Calculation of cumulative pitch (index), Fp	49
9.3.5	Calculation of single pitch, fpi	50
9.3.6	Calculation of total cumulative pitch deviation, Fp	50
9.3.7	Calculation of sector pitch deviation, Fpk	50
9.3.8	Segment gear measurement	50
9.4	Radial runout, determining eccentricity	51
9.4.1	Measuring principle	51
9.4.2	Evaluation of measurement	51
10	Interpretation of profile, helix, pitch and radial runout results	52
10.1	Interpreting measurement results	52
10.2	Procedure for interpreting measurement results	52
10.3	Recognition of common manufacturing errors	53
10.3.1	General	53
10.3.2	Example of a profile with pressure angle deviation	53
10.3.3	Example of profile deviations with varying pressure angle deviation	53
10.3.4	Hob runout or shaping cutter deflection	54
10.3.5	Consistent mean helix slope deviation	55
10.3.6	Helix slope variation	55
10.3.7	Profile control diameter not achieved	56
10.3.8	Variation in profile non-clean up and profile control diameter not achieved	56
10.3.9	Pitch results with radial runout of the gear blank	58
10.3.10	Pitch with indexing deviations	58
10.3.11	Pitch with repeating deviation patterns that may cause noise	61
11	Single flank composite testing	61
11.1	Single flank composite testing principle	61
11.2	Single flank composite test	62
11.2.1	Single flank test setup	62
11.2.2	Single flank composite deviations	64

11.3	Single flank measurement with master gear	65
11.3.1	Master gear requirements	65
11.3.2	Influence of profile deviations	65
11.3.3	Influence of pitch deviations	66
11.3.4	Influence of helix deviations	66
11.4	Single flank measurement of product gear pair	69
11.4.1	Differences between tests with a master gear and between two product gears	69
11.4.2	Identification and location of defects	69
11.4.3	Selective meshing of gears	69
11.5	Data analysis by the Fourier transform method	70
12	Additional measurements	71
12.1	Flank measurements	71
12.1.1	General	71
12.1.2	Twist measurement	71
12.1.3	Topographical measurement	72
12.1.4	Undulations	73
12.2	Surface roughness measurement	74
12.3	Tooth root fillet radius measurement	74
13	Filters and data density	75
13.1	General	75
13.2	Examples of filtered results	75
13.3	Working principle of the Gauss 50 % filter	75
13.4	Filter limitations	81
14	Additional calculations	81
14.1	Calculation of single pitch deviation, f_{pt} , from normal base pitch measurements	81
14.2	Additional calculations for normal base pitch measurements	82
14.2.1	Included parameters	82
14.2.2	Calculation of normal base pitch deviation, f_{pbn}	82
14.2.3	Calculation of mean normal base pitch deviation, f_{pbnm}	82
14.3	Additional calculations for profile measurements	82
14.3.1	Included parameters	82
14.3.2	Mean base diameter deviation and mean pressure angle deviation	83
14.3.3	Calculation of effective base diameter, $d_{b\text{ eff}}$	84
14.3.4	Calculation of effective transverse pressure angle, $t_{\text{ eff}}$	84
14.3.5	Calculation of effective normal pressure angle, $n_{\text{ eff}}$	84
14.3.6	Calculation of mean transverse pressure angle deviation, f_{mt}	85
14.3.7	Calculation of mean normal pressure angle deviation, f_{mn}	85
14.4	Additional calculations for helix measurements	85
14.4.1	Included parameters	85
14.4.2	Required preliminary data	86
14.4.3	Calculation of effective helix angle at the measurement diameter, $M_{\text{ eff}}$	86
14.4.4	Calculation of effective lead, $p_{z\text{ eff}}$	86
14.4.5	Calculation of effective helix angle at the standard pitch diameter, eff	87
14.4.6	Calculation of mean lead deviation, f_{pzm}	87
14.4.7	Calculation of mean helix angle deviation, f_m	87
	Bibliography	89