

# ISO 15531-44:2017-07 (E)

## Industrial automation systems and integration - Industrial manufacturing management data - Part 44: Information modelling for shop floor data acquisition

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions, and abbreviated terms .....</b>	<b>1</b>
<b>3.1</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3.2</b>	<b>Abbreviated terms .....</b>	<b>4</b>
<b>5</b>	<b>Purpose, principles and structure of this document .....</b>	<b>6</b>
<b>5.1</b>	<b>Purpose of this document .....</b>	<b>6</b>
<b>5.2</b>	<b>Basic principles of this document and overview of the main entities .....</b>	<b>6</b>
<b>5.3</b>	<b>Structure of shop floor data acquisition system .....</b>	<b>8</b>
<b>5.4</b>	<b>The captured data and their organization .....</b>	<b>9</b>
<b>5.4.1</b>	<b>General characteristics .....</b>	<b>9</b>
<b>5.4.2</b>	<b>Manufacturing management data .....</b>	<b>11</b>
<b>5.4.3</b>	<b>Quality management .....</b>	<b>11</b>
<b>5.4.4</b>	<b>Productivity and maintenance .....</b>	<b>11</b>
<b>5.4.5</b>	<b>Traceability .....</b>	<b>11</b>
<b>5.5</b>	<b>The question of time: time stamping and time measure .....</b>	<b>11</b>
<b>5.6</b>	<b>Size optimization .....</b>	<b>12</b>
<b>6</b>	<b>The EXPRESS schema definition of shop floor captured data .....</b>	<b>12</b>
<b>6.1</b>	<b>Shop floor captured data schema definition .....</b>	<b>12</b>
<b>6.2</b>	<b>Shopfloor_captured_data type definitions .....</b>	<b>13</b>
<b>6.2.1</b>	<b>type_of_movement .....</b>	<b>13</b>
<b>6.2.2</b>	<b>stock_in .....</b>	<b>13</b>
<b>6.2.3</b>	<b>stock_out .....</b>	<b>13</b>
<b>6.2.4</b>	<b>stock_taking .....</b>	<b>14</b>
<b>6.3</b>	<b>Shop floor captured data entity definitions .....</b>	<b>14</b>
<b>6.3.1</b>	<b>Stock .....</b>	<b>14</b>
<b>6.3.2</b>	<b>Manufactured_product .....</b>	<b>14</b>
<b>6.3.3</b>	<b>Orders .....</b>	<b>15</b>
<b>6.3.4</b>	<b>Manufacturing_batch .....</b>	<b>16</b>
<b>6.3.5</b>	<b>Work_order .....</b>	<b>16</b>
<b>6.3.6</b>	<b>material_consumption .....</b>	<b>17</b>
<b>6.3.7</b>	<b>Productivity_and_maintenance .....</b>	<b>18</b>
<b>6.3.8</b>	<b>Quality .....</b>	<b>20</b>
<b>6.3.9</b>	<b>Resource .....</b>	<b>21</b>
<b>6.3.10</b>	<b>Time stamping and time reference .....</b>	<b>22</b>
	<b>Annex A (normative) Information object registration .....</b>	<b>23</b>
	<b>Annex B (informative) EXPRESS listing .....</b>	<b>24</b>
	<b>Annex C (informative) EXPRESS-G Diagram .....</b>	<b>28</b>
	<b>Bibliography .....</b>	<b>30</b>