

# ISO 19085-13:2020-05 (E)

## Woodworking machines - Safety - Part 13: Multi-blade rip sawing machines with manual loading and/or unloading

---

### Contents

Page

Foreword	v
Introduction	vi
<b>1 Scope</b>	<b>1</b>
<b>2 Normative references</b>	<b>1</b>
<b>3 Terms and definitions</b>	<b>2</b>
<b>4 List of significant hazards</b>	<b>4</b>
<b>5 Safety requirements and measures for controls</b>	<b>6</b>
5.1 Safety and reliability of control systems	6
5.2 Control devices	6
5.3 Start	8
5.4 Safe stops	8
5.4.1 General	8
5.4.2 Normal stop	8
5.4.3 Operational stop	8
5.4.4 Emergency stop	8
5.5 Braking function of tool spindles	8
5.6 Mode selection	8
5.6.1 General	8
5.6.2 Pressure shoe/board cutting mode	8
5.6.3 Cleaning mode	9
5.6.4 Powered axial adjustment mode	9
5.7 Spindle speed changing	10
5.7.1 Spindle speed changing by changing belts on the pulleys	10
5.7.2 Spindle speed changing by incremental speed change motor	10
5.7.3 Infinitely variable speed by frequency inverter	10
5.8 Failure of any power supply	10
5.9 Manual reset control	10
5.10 Enabling control	10
5.11 Machine moving parts limited speed monitoring	10
5.12 Time delay	10
5.13 Powered adjustments when guards are closed	10
<b>6 Safety requirements and measures for protection against mechanical hazards</b>	<b>11</b>
6.1 Stability	11
6.1.1 Stationary machines	11
6.1.2 Displaceable machines	11
6.2 Risk of break-up during operation	11
6.3 Tool holder and tool design	11
6.3.1 General	11
6.3.2 Spindle locking	11
6.3.3 Circular saw blade fixing device	11
6.3.4 Flanges dimensions for circular saw blades	11
6.4 Braking	11
6.4.1 Braking of tool spindles	11
6.4.2 Maximum run-down time	12
6.4.3 Brake release	12
6.5 Safeguard design	12
6.5.1 Fixed guards	12

6.5.2	Interlocking moveable guards.....	12
6.5.3	Hold-to-run control.....	12
6.5.4	Two-hand control.....	12
6.5.5	Electro-sensitive protective equipment (ESPE).....	12
6.5.6	Pressure sensitive protective equipment (PSPE).....	12
6.6	Prevention of access to moving parts.....	12
6.6.1	General.....	12
6.6.2	Guarding of tools.....	13
6.6.3	Guarding of drives.....	13
6.6.4	Guarding of crushing and shearing zones.....	13
6.7	Impact hazard.....	14
6.8	Clamping devices.....	14
6.9	Measures against ejection.....	14
6.9.1	General.....	14
6.9.2	Guards materials and characteristics.....	14
6.9.3	Measures against ejection through the infeed opening.....	15
6.9.4	Measures against ejection through the outfeed opening.....	25
6.10	Work-piece support and guide.....	28
<b>7</b>	<b>Safety requirements and measures for protection against other hazards.....</b>	<b>28</b>
7.1	Fire.....	28
7.2	Noise.....	28
7.2.1	Noise reduction at the design stage.....	28
7.2.2	Noise emission measurement.....	28
7.3	Emission of chips and dust.....	28
7.4	Electricity.....	28
7.4.1	General.....	28
7.4.2	Displaceable machines.....	28
7.5	Ergonomics and handling.....	28
7.6	Lighting.....	28
7.7	Pneumatics.....	29
7.8	Hydraulics.....	29
7.9	Electromagnetic compatibility.....	29
7.10	Laser.....	29
7.11	Static electricity.....	29
7.12	Errors of fitting.....	29
7.13	Isolation.....	29
7.14	Maintenance.....	29
<b>8</b>	<b>Information for use.....</b>	<b>29</b>
8.1	Warning devices.....	29
8.2	Marking.....	29
8.2.1	General.....	29
8.2.2	Additional marking.....	29
8.3	Instruction handbook.....	30
8.3.1	General.....	30
8.3.2	Additional information.....	30
	<b>Annex A (informative) Performance level required.....</b>	<b>31</b>
	<b>Annex B (normative) Test for braking function.....</b>	<b>32</b>
	<b>Annex C (normative) Stability test for displaceable machines.....</b>	<b>33</b>
	<b>Annex D (normative) Impact test method for guards.....</b>	<b>34</b>
	<b>Annex E (normative) Noise emission measurement for machines not in ISO 7960:1995.....</b>	<b>35</b>
	<b>Annex F (normative) Test for the anti-splinter system on machines with one chain conveyor.....</b>	<b>36</b>
	<b>Bibliography.....</b>	<b>40</b>

**Annex F (normative) Test for the anti-splinter system on machines with one chain conveyor .....36**  
**Bibliography .....40**