

# DIN EN 1822-4:2001-02 (E)

## High efficiency particulate air filters (HEPA and ULPA) - Part 4: Determining leakage of filter elements (Scan method); English version of DIN EN 1822-4

---

### Contents

	Page
Foreword .....	3
Introduction .....	3
1 Scope .....	4
2 Normative references .....	4
3 Terms and definitions.....	4
3.1 sampling volume flow rate .....	4
3.2 sampling duration .....	5
3.3 total particle count method .....	5
3.4 particle counting and sizing method.....	5
3.5 particle flow rate .....	5
3.6 particle flow distribution.....	5
4 Description of the procedure .....	5
5 Test filter .....	6
6 Test apparatus.....	7
6.1 Set-up of the test apparatus.....	7
6.2 Test duct.....	9
6.3 Scanning assembly.....	10
6.4 Aerosol generation and measurement techniques.....	11
7 Test air .....	13
8 Test procedure .....	13
8.1 General .....	13
8.2 Preparatory checks .....	14
8.3 Starting up the aerosol generator .....	14
8.4 Preparing the test filter.....	15
8.5 Testing .....	15
9 Evaluation.....	17
9.1 Calculating the penetration and the efficiency.....	17
9.2 Local penetration.....	19
9.3 Mean efficiency .....	19
9.4 Classification.....	19
10 Test report.....	19
10.1 Details of the test filter .....	19
10.2 General details of the test parameters .....	19
10.3 Test results.....	20
11 Maintenance and inspection of the test apparatus .....	20
Annex A (normative) Oil thread test .....	22
Annex B (normative) Determining the test parameters .....	23
Annex C (informative) Example of an application with evaluation .....	33
Bibliography .....	35