

ISO 19085-6:2024-04 (E)

Woodworking machines - Safety - Part 6: Single spindle vertical moulding machines (toupie)

Contents

Page

Foreword.....	vi
Introduction.....	vii
1 Scope.....	1
2 Normative references.....	2
3 Terms and definitions.....	2
4 Safety requirements and measures for controls.....	9
4.1 Safety and reliability of control systems.....	9
4.2 Control devices.....	9
4.3 Start.....	10
4.3.1 Direct start.....	10
4.3.2 Start via control power-on.....	10
4.4 Safe stops.....	11
4.4.1 General.....	11
4.4.2 Normal stop.....	11
4.4.3 Operational stop.....	11
4.4.4 Emergency stop.....	11
4.5 Braking function of tools.....	11
4.6 Mode selection.....	11
4.7 Tool speed changing.....	11
4.7.1 Speed changing by shifting the belts on the pulleys.....	11
4.7.2 Speed changing by incremental speed change motor.....	11
4.7.3 Infinitely variable speed by frequency inverter.....	11
4.7.4 Speed limiting device for tenoning.....	11
4.7.5 Changing the direction of tool rotation.....	12
4.8 Failure of any power supply.....	12
4.9 Manual reset control.....	13
4.10 Standstill detection and monitoring.....	13
4.11 Machine moving parts speed monitoring.....	13
4.12 Time delay.....	13
4.13 Teleservice.....	13
4.14 Power-driven adjustment of arbor, demountable power feed unit, fences and table insert.....	13
5 Safety requirements and measures for protection against mechanical hazards.....	14
5.1 Stability.....	14
5.2 Risk of break-up during operation.....	14
5.3 Tool and tool fixing design.....	14
5.3.1 General.....	14
5.3.2 Spindle locking.....	17
5.3.3 Circular saw blade fixing device.....	17
5.3.4 Flange dimension for circular saw blades.....	17
5.3.5 Arbor rings.....	17
5.3.6 Quick tool/arbor change system.....	17
5.3.7 Manual adjustment of arbor height.....	18
5.3.8 Manual adjustment of arbor inclination.....	18
5.4 Braking.....	19
5.4.1 Braking of tools.....	19
5.4.2 Maximum run-down time.....	19
5.4.3 Brake release.....	19
5.5 Safeguards.....	19

5.5.1	Fixed guards.....	19
5.5.2	Interlocking movable guards	19
5.5.3	Hold-to-run control.....	19
5.5.4	Two-hand control.....	19
5.5.5	Electro-sensitive protective equipment (ESPE)	19
5.5.6	Pressure-sensitive protective equipment (PSPE).....	19
5.5.7	Enabling control.....	20
5.6	Prevention of access to hazardous moving parts.....	20
5.6.1	Access to the tool below the table.....	20
5.6.2	Safeguarding for straight work.....	20
5.6.3	Safeguarding for curved work.....	22
5.6.4	Safeguarding for tenoning.....	23
5.6.5	Safeguarding the glass bead saw blade.....	24
5.6.6	Guarding of drives.....	24
5.7	Impact hazard.....	24
5.8	Clamping devices.....	24
5.9	Measures against ejection.....	24
5.9.1	General.....	24
5.9.2	Guards materials and characteristics.....	24
5.9.3	Anti-kickback devices.....	25
5.10	Workpiece supports and guides.....	27
5.10.1	Machine table.....	27
5.10.2	Workpiece guiding for straight work.....	30
5.10.3	Workpiece guiding for curved work.....	31
5.11	Safety appliances.....	32
6	Safety requirements and measures for protection against other hazards.....	32
6.1	Fire.....	32
6.2	Noise.....	32
6.2.1	Noise reduction at the design stage.....	32
6.2.2	Noise emission measurement and declaration.....	33
6.3	Emission of chips and dust.....	33
6.4	Electricity.....	33
6.5	Ergonomics and handling.....	33
6.6	Lighting.....	33
6.7	Pneumatics.....	33
6.8	Hydraulics.....	34
6.9	Electromagnetic compatibility.....	34
6.10	Laser.....	34
6.11	Static electricity.....	34
6.12	Errors of fitting.....	34
6.13	Isolation.....	34
6.14	Maintenance.....	34
6.15	Relevant but not significant hazards.....	34
7	Information for use.....	34
7.1	Warning devices.....	34
7.2	Marking.....	34
7.2.1	General.....	34
7.2.2	Additional markings.....	34
7.3	Instruction handbook.....	35
7.3.1	General.....	35
7.3.2	Additional information.....	35
	Annex A (informative) List of significant hazards.....	38
	Annex B (informative) Performance level required.....	40
	Annex C (normative) Stability test.....	41
	Annex D (normative) Test for braking function.....	42
	Annex E (normative) Impact test for guards.....	43
	Annex F (normative) Noise test code.....	44
	Annex G (informative) Determination of maximum spindle speeds for single piece arbors.....	47
	Annex H (normative) Rigidity test for pressure pads, hand protectors and guiding steadies.....	51
	Bibliography.....	57