

# ISO 14695:2003-04 (E)

## Industrial fans - Method of measurement of fan vibration

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Symbols and units .....</b>	<b>2</b>
<b>5</b>	<b>Mounting of test rig .....</b>	<b>4</b>
<b>5.1</b>	<b>General .....</b>	<b>4</b>
<b>5.2</b>	<b>Resilient base mounting of fan .....</b>	<b>5</b>
<b>5.3</b>	<b>Mounting of fans with resilient elastic rope .....</b>	<b>5</b>
<b>5.4</b>	<b>Stiff mounting of fans .....</b>	<b>9</b>
<b>5.5</b>	<b>Flexible connections .....</b>	<b>9</b>
<b>6</b>	<b>Measuring equipment .....</b>	<b>9</b>
<b>6.1</b>	<b>General .....</b>	<b>9</b>
<b>6.2</b>	<b>Calibration .....</b>	<b>9</b>
<b>6.3</b>	<b>Instrument system .....</b>	<b>10</b>
<b>6.4</b>	<b>Transducers .....</b>	<b>10</b>
<b>6.5</b>	<b>Piezoelectric accelerometers .....</b>	<b>11</b>
<b>6.6</b>	<b>Preamplifiers .....</b>	<b>11</b>
<b>6.7</b>	<b>Analysers .....</b>	<b>11</b>
<b>6.8</b>	<b>Indicators .....</b>	<b>12</b>
<b>6.9</b>	<b>Outputs .....</b>	<b>12</b>
<b>7</b>	<b>Transducer attachment .....</b>	<b>12</b>
<b>7.1</b>	<b>General .....</b>	<b>12</b>
<b>7.2</b>	<b>Attachments .....</b>	<b>13</b>
<b>8</b>	<b>Selection of measuring positions .....</b>	<b>13</b>
<b>8.1</b>	<b>General .....</b>	<b>13</b>
<b>8.2</b>	<b>Mounting on combination base frame .....</b>	<b>16</b>
<b>8.3</b>	<b>Mounting of transducers for other fans .....</b>	<b>16</b>
<b>9</b>	<b>Test environment and operating data .....</b>	<b>16</b>
<b>10</b>	<b>Procedure .....</b>	<b>16</b>
<b>10.1</b>	<b>General .....</b>	<b>16</b>
<b>10.2</b>	<b>Measurement parameters .....</b>	<b>17</b>
<b>10.3</b>	<b>Frequency analysis .....</b>	<b>18</b>
<b>11</b>	<b>Presentation of results .....</b>	<b>18</b>
<b>Annex A (informative)</b>	<b>Guide to calculating resilient mount positions and rigid body natural frequencies .....</b>	<b>19</b>
<b>Annex B (informative)</b>	<b>Secondary measurement methods for in situ testing or quality grading .....</b>	<b>25</b>

<b>Annex C (informative) Recommended measuring positions for machinery health measurements ....</b>	<b>27</b>
<b>Annex D (informative) Relationship between absolute and decibel levels .....</b>	<b>29</b>
<b>Annex E (informative) Relationship between vibration magnitude of single frequency signal .....</b>	<b>31</b>
<b>Bibliography .....</b>	<b>33</b>