

ISO 22127:2019-12 (E)

Dosimetry with radiophotoluminescent glass dosimeters for dosimetry audit in MV X-ray radiotherapy

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Rules for the RPLD handling/reading procedure	5
4.1	Principle of measurement	5
4.2	Objective quantity of measurement	6
4.3	Handling of RPLDs	6
4.3.1	General remarks	6
4.3.2	Cleaning of RPLD element	6
4.4	Annealing	6
4.5	Irradiation of RPLD	6
4.5.1	Effective centre of measurement	6
4.5.2	Irradiation dose	6
4.6	Pre-heating	6
4.7	RPLD Reading	7
4.7.1	General remarks	7
4.7.2	Positioning RPLD elements on the reading tray	7
4.7.3	Determination of the RPL reading	7
4.7.4	Reader stability compensation by reference RPLDs	7
5	Evaluation of absorbed dose to water	7
5.1	Basic formula for the determination of absorbed dose to water	7
5.2	Mean readings of raw data	8
5.3	Evaluation of background element	8
5.4	Individual dosimeter sensitivity correction factor of each element	8
5.5	Calibration coefficient with reference RPLD element	8
5.6	Correction factor for individual reading tray position dependence	9
5.7	Correction factor for the radiation quality	9
5.8	Correction factor for phantom material	10
5.9	Correction factor for nonlinearity	10
5.10	Uncertainty of measurement of the absorbed dose	11
6	Requirements for the RPLD system	11
6.1	General information	11
6.2	Recommendations concerning completeness of the RPLD system	11
6.2.1	Technical components	11
6.2.2	Hardware and software components	12
6.2.3	Operating instructions	12
6.3	Requirements for RPLD detectors	13
6.3.1	Characteristics of RPLD materials	13
6.4	Requirements for RPLD-indicating instruments	14
6.4.1	General remarks	14
6.4.2	Mechanical construction and setup	14
6.4.3	Repeatable reading ability	14

6.4.4	Indication and indication range	14
6.4.5	Internal calibration glass	14
6.4.6	Operational failure and detection	14
6.4.7	Data output and data backup	15
6.5	Requirements for auxiliary instruments (pre-irradiation annealing and pre-heat devices) .	15
6.5.1	Pre-irradiation annealing	15
6.5.2	Pre-heat	15
6.5.3	Operation safety	15
6.5.4	Detection of function failure	15
6.5.5	Indication of the operating state	15
	Bibliography	16