

# ISO 14347:2008-12 (E)

## Fatigue - Design procedure for welded hollow-section joints - Recommendations

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
1.1	General .....	1
1.2	Materials .....	1
1.3	Types of joints .....	1
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Symbols and abbreviated terms .....</b>	<b>7</b>
<b>5</b>	<b>Cumulative fatigue damage .....</b>	<b>12</b>
<b>6</b>	<b>Partial safety factor .....</b>	<b>12</b>
<b>7</b>	<b>Fatigue design procedures .....</b>	<b>12</b>
7.1	Hot-spot stress method .....	12
7.2	Design procedures .....	13
<b>8</b>	<b>Fatigue strength .....</b>	<b>13</b>
8.1	Member forces .....	13
8.2	Nominal stress ranges .....	14
8.3	SCF calculations .....	14
8.4	Hot-spot stress ranges .....	14
8.5	Fatigue strength curves .....	15
<b>9</b>	<b>SCF calculations for CHS joints .....</b>	<b>17</b>
9.1	Uniplanar CHS T- and Y-joints .....	17
9.2	Uniplanar CHS X-joints .....	18
9.3	Uniplanar CHS K-joints with gap .....	18
9.4	Multiplanar CHS XX-joints .....	19
9.5	Multiplanar CHS KK-joints with gap .....	20
9.6	Minimum SCF values .....	21
<b>10</b>	<b>SCF calculations for RHS joints .....</b>	<b>21</b>
10.1	Uniplanar RHS T- and X-joints .....	21
10.2	Uniplanar RHS K-joints with gap .....	22
10.3	Uniplanar RHS K-joints with overlap .....	23
10.4	Multiplanar RHS KK-joints with gap .....	24
10.5	Minimum SCF values .....	25
<b>Annex A (normative)</b>	<b>Quality requirements for hollow sections .....</b>	<b>26</b>
<b>Annex B (normative)</b>	<b>Weld details .....</b>	<b>27</b>
<b>Annex C (informative)</b>	<b>A fatigue assessment procedure .....</b>	<b>29</b>
<b>Annex D (normative)</b>	<b>SCF equations and graphs for CHS joints .....</b>	<b>31</b>
<b>Annex E (normative)</b>	<b>SCF equations and graphs for RHS joints .....</b>	<b>47</b>
<b>Bibliography .....</b>		<b>67</b>