

ISO 13916:1996-08 (E)

Welding - Guidance on the measurement of preheating temperature, interpass temperature and preheat maintenance temperature

Contents		Page
Foreword		IV
1 Scope		1
2 Definitions		1
2.1 Preheating temperature (T_p)		1
2.2 Interpass temperature (T_i)		1
2.3 Preheat maintenance temperature (T_m)		1
3 Requirements		1
3.1 Point of measurement		1
3.2 Time of measurement		2
3.3 Test equipment		3
4 Test report		3
5 Designation		3