

# ISO 13916:1996-08 (E)

## Welding - Guidance on the measurement of preheating temperature, interpass temperature and preheat maintenance temperature

---

<b>Contents</b>		<b>Page</b>
Foreword .....		IV
<b>1</b> Scope .....		<b>1</b>
<b>2</b> Definitions .....		<b>1</b>
2.1 Preheating temperature ( $T_p$ ) .....		1
2.2 Interpass temperature ( $T_i$ ) .....		1
2.3 Preheat maintenance temperature ( $T_m$ ) .....		1
<b>3</b> Requirements .....		<b>1</b>
3.1 Point of measurement .....		1
3.2 Time of measurement .....		2
3.3 Test equipment .....		3
<b>4</b> Test report .....		<b>3</b>
<b>5</b> Designation .....		<b>3</b>