

# DIN EN ISO 21904-3:2018-07 (E)

Health and safety in welding and allied processes - Requirements, testing and marking of equipment for air filtration - Part 3: Determination of the capture efficiency of on-torch welding fume extraction devices (ISO 21904-3:2018)

---

<b>Contents</b>	<b>Page</b>
European foreword .....	3
Foreword .....	4
Introduction .....	5
<b>1 Scope</b> .....	<b>6</b>
<b>2 Normative references</b> .....	<b>6</b>
<b>3 Terms and definitions</b> .....	<b>6</b>
<b>4 Principle</b> .....	<b>7</b>
<b>5 Test equipment and materials</b> .....	<b>7</b>
5.1 General requirement .....	7
5.2 Test equipment .....	7
<b>6 Test procedure</b> .....	<b>9</b>
6.1 Preliminary tests .....	9
6.1.1 Setting the shielding gas flow rate .....	9
6.1.2 Measuring the flow rates and determination of leakage .....	9
6.1.3 Establishing the arcing time for total fume emission rate test .....	10
6.1.4 Setting up the test equipment .....	10
6.2 Capture efficiency tests .....	11
6.2.1 General .....	11
6.2.2 Test procedure .....	11
6.2.3 Calculation of the results .....	12
<b>7 Test parameters for generating capture efficiency data</b> .....	<b>13</b>
<b>8 Test report</b> .....	<b>14</b>
<b>Annex A (informative) Equipment notes</b> .....	<b>15</b>
<b>Annex B (normative) Trial tests</b> .....	<b>17</b>
<b>Annex C (informative) Examples of test chambers</b> .....	<b>19</b>
<b>Annex D (normative) Test procedures</b> .....	<b>21</b>
<b>Annex E (informative) Data processing for test method 3</b> .....	<b>22</b>
<b>Annex F (normative) Test parameters form to be filled</b> .....	<b>24</b>
<b>Annex G (informative) Information about the necessity to measure leakage</b> .....	<b>25</b>
<b>Bibliography</b> .....	<b>26</b>