

ISO 5171:2019 (E)

Gas welding equipment — Pressure gauges used in welding, cutting and allied processes

Contents

| | |
|-----------|--|
| | Foreword |
| 1 | Scope |
| 2 | Normative references |
| 3 | Terms and definitions |
| 4 | Pressure |
| 4.1 | Unit of pressure |
| 4.2 | Maximum scale reading |
| 4.3 | Maximum pressure mark |
| 5 | Manufacturing requirements |
| 5.1 | Materials |
| 5.1.1 | General |
| 5.1.2 | Oxygen pressure gauges |
| 5.2 | Design and dimensions |
| 5.2.1 | Operational equipment |
| 5.2.1.1 | Accuracy |
| 5.2.1.2 | Overpressure and leakage test requirements |
| 5.2.1.2.1 | General |
| 5.2.1.2.2 | Test A |
| 5.2.1.2.3 | Test B |
| 5.2.1.3 | Torsion |
| 5.2.1.4 | Bending |
| 5.2.1.5 | Case vent test |
| 5.2.2 | Dimensions |
| 5.2.3 | Dial and pointer |
| 6 | Safety |
| 7 | Marking |
| 8 | Tests |
| 8.1 | General |
| 8.2 | Accuracy |
| 8.3 | Torsion test |
| 8.4 | Bend test |
| 8.5 | Case vent test |
| 8.6 | Overpressure and leakage test |
| 8.6.1 | Test A |
| 8.6.2 | Test B |
| 8.7 | Flammability test |

Page count: 15