

ISO 5171:2019 (E)

Gas welding equipment — Pressure gauges used in welding, cutting and allied processes

Contents

	Foreword
1	Scope
2	Normative references
3	Terms and definitions
4	Pressure
4.1	Unit of pressure
4.2	Maximum scale reading
4.3	Maximum pressure mark
5	Manufacturing requirements
5.1	Materials
5.1.1	General
5.1.2	Oxygen pressure gauges
5.2	Design and dimensions
5.2.1	Operational equipment
5.2.1.1	Accuracy
5.2.1.2	Overpressure and leakage test requirements
5.2.1.2.1	General
5.2.1.2.2	Test A
5.2.1.2.3	Test B
5.2.1.3	Torsion
5.2.1.4	Bending
5.2.1.5	Case vent test
5.2.2	Dimensions
5.2.3	Dial and pointer
6	Safety
7	Marking
8	Tests
8.1	General
8.2	Accuracy
8.3	Torsion test
8.4	Bend test
8.5	Case vent test
8.6	Overpressure and leakage test
8.6.1	Test A
8.6.2	Test B
8.7	Flammability test

Page count: 15