

ISO 17846:2004-05 (E)

Welding and allied processes - Health and safety - Wordless precautionary labels for equipment and consumables used in arc welding and cutting

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Requirements for wordless precautionary labels	2
4.1	Use of precautionary labels on products	2
4.2	Label elements	2
4.3	Design of precautionary labels	2
4.4	Use of symbols	2
4.5	Uniformity of symbols	2
4.6	Label legibility, placement, visibility, and durability	3
4.7	The basic precautionary label	3
4.8	The wordless label for plasma arc cutting equipment	3
4.9	The precautionary label for engine-driven welding and cutting equipment	3
4.10	The precautionary label for wire feeding equipment	3
4.11	Precautionary labels for other hazards	3
	Annex A (informative) Precautionary label symbols	4
	Annex B (informative) Examples of wordless precautionary labels	10
	Bibliography	18