

ISO 17846:2004-05 (E)

Welding and allied processes - Health and safety - Wordless precautionary labels for equipment and consumables used in arc welding and cutting

| Contents | | Page |
|---|---|-------------|
| Foreword | | iv |
| Introduction | | v |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 4 | Requirements for wordless precautionary labels | 2 |
| 4.1 | Use of precautionary labels on products | 2 |
| 4.2 | Label elements | 2 |
| 4.3 | Design of precautionary labels | 2 |
| 4.4 | Use of symbols | 2 |
| 4.5 | Uniformity of symbols | 2 |
| 4.6 | Label legibility, placement, visibility, and durability | 3 |
| 4.7 | The basic precautionary label | 3 |
| 4.8 | The wordless label for plasma arc cutting equipment | 3 |
| 4.9 | The precautionary label for engine-driven welding and cutting equipment | 3 |
| 4.10 | The precautionary label for wire feeding equipment | 3 |
| 4.11 | Precautionary labels for other hazards | 3 |
| Annex A (informative) Precautionary label symbols | | 4 |
| Annex B (informative) Examples of wordless precautionary labels | | 10 |
| Bibliography | | 18 |