

# ISO 15614-10:2005-02 (E)

## Specification and qualification of welding procedures for metallic materials - Welding procedure test - Part 10: Hyperbaric dry welding

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>4</b>	<b>Preliminary welding procedure specification (pWPS) .....</b>	<b>2</b>
<b>5</b>	<b>Welding procedure test .....</b>	<b>3</b>
<b>6</b>	<b>Test piece .....</b>	<b>3</b>
<b>6.1</b>	<b>General .....</b>	<b>3</b>
<b>6.2</b>	<b>Shape and dimensions of test pieces .....</b>	<b>3</b>
<b>6.3</b>	<b>Welding of test pieces .....</b>	<b>3</b>
<b>7</b>	<b>Examination and testing .....</b>	<b>4</b>
<b>7.1</b>	<b>Extent of testing .....</b>	<b>4</b>
<b>7.2</b>	<b>Location and cutting of test specimens .....</b>	<b>4</b>
<b>7.3</b>	<b>Non-destructive testing .....</b>	<b>4</b>
<b>7.4</b>	<b>Destructive tests .....</b>	<b>4</b>
<b>7.5</b>	<b>Re-testing .....</b>	<b>4</b>
<b>8</b>	<b>Range of qualification .....</b>	<b>4</b>
<b>8.1</b>	<b>General .....</b>	<b>4</b>
<b>8.2</b>	<b>Related to the manufacturer .....</b>	<b>5</b>
<b>8.3</b>	<b>Related to the parent material .....</b>	<b>5</b>
<b>8.4</b>	<b>Common to all welding procedures .....</b>	<b>5</b>
<b>8.5</b>	<b>Specific to processes .....</b>	<b>7</b>
<b>8.6</b>	<b>Specific to hyperbaric environment .....</b>	<b>7</b>
<b>9</b>	<b>Welding procedure qualification record (WPQR) .....</b>	<b>8</b>