

# ISO 21438-1:2007-12 (E)

## Workplace atmospheres - Determination of inorganic acids by ion chromatography - Part 1: Non-volatile acids (sulfuric acid and phosphoric acid)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	2
3.1	General definitions .....	2
3.2	Particle size fraction definitions .....	3
3.3	Sampling definitions .....	3
3.4	Analytical definitions .....	4
3.5	Statistical terms .....	5
4	Principle .....	6
5	Requirement .....	7
6	Reagents .....	7
7	Apparatus .....	9
7.1	Sampling equipment .....	9
7.2	Laboratory apparatus .....	11
8	Occupational exposure assessment .....	12
8.1	General .....	12
8.2	Personal sampling .....	12
8.3	Static sampling .....	12
8.4	Selection of measurement conditions and measurement pattern .....	13
9	Sampling .....	14
9.1	Preliminary considerations .....	14
9.2	Preparation for sampling .....	16
9.3	Sampling position .....	16
9.4	Collection of samples .....	17
9.5	Transportation .....	17
10	Analysis .....	18
10.1	Preparation of test and calibration solutions .....	18
10.2	Instrumental analysis .....	19
10.3	Estimation of detection and quantification limits .....	20
10.4	Quality control .....	21
10.5	Measurement uncertainty .....	21
11	Expression of results .....	22
12	Method performance .....	22
12.1	Sample collection and stability .....	22
12.2	Quantification limits .....	22
12.3	Upper limits of the analytical range .....	22

12.4	Bias and precision .....	23
12.5	Uncertainty of sampling and analysis method .....	23
12.6	Interferences .....	23
13	Test report .....	24
13.1	Test record .....	24
13.2	Laboratory report .....	25
Annex A (informative) Temperature and pressure correction .....		26
Bibliography .....		28