

# DIN EN 15051-3:2014-03 (E)

## Workplace exposure - Measurement of the dustiness of bulk materials - Part 3: Continuous drop method

---

| <b>Contents</b>    |  | <b>Page</b> |
|--------------------|--|-------------|
| Foreword .....     |  | 3           |
| Introduction ..... |  | 4           |
| 1                  | Scope .....  | 5           |
| 2                  | Normative references .....   | 5           |
| 3                  | Terms and definitions .....  | 5           |
| 4                  | Requirements .....   | 6           |
| 4.1                | General .....  | 6           |
| 4.2                | Condition of the bulk material .....   | 6           |
| 4.3                | Sample and environmental control .....                                       | 6           |
| 4.4                | Moisture content .....   | 6           |
| 4.5                | Bulk density .....   | 6           |
| 4.6                | Test procedure .....   | 6           |
| 4.7                | Replicate tests .....  | 6           |
| 4.8                | Reporting .....  | 6           |
| 5                  | Continuous drop method .....   | 6           |
| 5.1                | Description of test apparatus .....  | 6           |
| 5.2                | Filters .....  | 8           |
| 5.3                | Ancillary equipment .....  | 8           |
| 5.4                | Preparation of test sample .....   | 8           |
| 5.5                | Preparation of test apparatus .....  | 9           |
| 5.6                | Test procedure .....   | 9           |
| 5.7                | Weighing the filters .....   | 9           |
| 5.8                | Determination of the inhalable and respirable dustiness mass fractions ..... | 10          |
| 6                  | Evaluation of dustiness .....  | 10          |
| 7                  | Test report .....  | 11          |
| Bibliography ..... |  | 12          |