

DIN EN 15051-3:2014-03 (E)

Workplace exposure - Measurement of the dustiness of bulk materials - Part 3: Continuous drop method

Contents	Page
Foreword	3
Introduction	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	5
4 Requirements	6
4.1 General	6
4.2 Condition of the bulk material	6
4.3 Sample and environmental control	6
4.4 Moisture content	6
4.5 Bulk density	6
4.6 Test procedure	6
4.7 Replicate tests	6
4.8 Reporting	6
5 Continuous drop method	6
5.1 Description of test apparatus	6
5.2 Filters	8
5.3 Ancillary equipment	8
5.4 Preparation of test sample	8
5.5 Preparation of test apparatus	9
5.6 Test procedure	9
5.7 Weighing the filters	9
5.8 Determination of the inhalable and respirable dustiness mass fractions	10
6 Evaluation of dustiness	10
7 Test report	11
Bibliography	12