

ISO 17733:2015-12 (E)

Workplace air - Determination of mercury and inorganic mercury compounds - Method by cold- vapour atomic absorption spectrometry or atomic fluorescence spectrometry

Contents		Page
Foreword		vi
Introduction		vii
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
3.1	General definitions	2
3.2	Particle size fraction definitions	3
3.3	Sampling definitions	3
3.4	Analytical definitions	4
3.5	Statistical terms	6
4	Principle	7
5	Interferences	7
6	Requirement	8
7	Reagents	8
8	Apparatus	10
8.1	Sampling equipment for diffusive sampling	10
8.2	Sampling equipment for pumped sampling	11
8.3	Laboratory apparatus	14
8.4	Analytical instrumentation	16
9	Occupational exposure assessment	21
9.1	General	21
9.2	Personal sampling	21
9.3	Static (area) sampling	21
9.4	Selection of measurement conditions and measurement pattern	22
9.4.1	General	22
9.4.2	Screening measurements of variation of concentration in time and/or space	22
9.4.3	Screening measurements of time-weighted average concentration and worst case measurements	22
9.4.4	Measurements near an emission source	22
9.4.5	Measurements for comparison with limit values and periodic measurements	22
10	Sampling	23
10.1	Selection of sampling method	23
10.1.1	Measurement of mercury vapour	23
10.1.2	Measurement of particulate inorganic mercury compounds	23
10.1.3	Measurement of mercury vapour and particulate inorganic mercury compounds	23
10.2	Consideration of temperature and pressure effects	24
10.2.1	Effect of temperature and pressure on the uptake rate of diffusive badges	24

10.2.2	Effect of temperature and pressure on volumetric flow rate in the pumped sampling method	24
10.2.3	Expression of results	24
10.3	Diffusive sampling	24
10.3.1	Selection and use of diffusive badges	24
10.3.2	Preparation for sampling	25
10.3.3	Sampling position	26
10.3.4	Sample collection	26
10.3.5	Transportation of samples	26
10.4	Pumped sampling	27
10.4.1	Preliminary considerations	27
10.4.2	Preparation for sampling	28
10.4.3	Sampling position	29
10.4.4	Collection of samples	30
10.4.5	Transportation of samples	30
11	Analysis	31
11.1	General	31
11.2	Cleaning of glassware and plasticware	31
11.3	Preparation of blank, sample and calibration solutions for analysis of diffusive badges ..	31
11.3.1	Preparation of blank and sample solutions	31
11.3.2	Preparation of calibration solutions	32
11.4	Preparation of blank, sample and calibration solutions for analysis of pumped samples.33	
11.4.1	Preparation of blank and sample solutions	33
11.4.2	Preparation of calibration solutions	34
11.5	Instrumental analysis	35
11.5.1	Setting up the instrument	35
11.5.2	Introduction of solutions into the mercury cold-vapour generation system	36
11.5.3	Conditioning the mercury cold-vapour generation system	36
11.5.4	Check for contamination of the reagents and/or system	37
11.5.5	Calibration	37
11.5.6	Determination	38
11.6	Estimation of detection and quantification limits	39
11.6.1	Estimation of the instrumental detection limit	39
11.6.2	Estimation of the method detection limit and the quantification limit	39
11.7	Quality control	40
11.7.1	Reagent blanks and laboratory blanks	40
11.7.2	Quality control solutions	40
11.7.3	Certified reference materials (CRMs)	40
11.7.4	External quality assessment	40
11.8	Measurement uncertainty	40
12	Expression of results	41
12.1	Calculation of the volume of air samples	41
12.1.1	Diffusive sampling	41
12.1.2	Pumped sampling	41
12.2	Calculation of mercury in air concentrations	41
13	Method performance	42
13.1	General	42
13.2	Detection and quantification limits	42
13.2.1	Sampling with diffusive badges and analysis by cold-vapour atomic absorption spectrometry	42
13.2.2	Sampling with pumped sorbent tubes and analysis by cold-vapour atomic absorption spectrometry	42
13.2.3	Sampling with pumped sorbent tubes and analysis by cold-vapour atomic fluorescence spectrometry	42
13.2.4	Sampling with inhalable samplers and analysis by cold-vapour atomic absorption spectrometry	42
13.3	Upper limits of the analytical range	43
13.4	Blank values	43

13.5	Bias and precision	43
13.5.1	Analytical bias	43
13.5.2	Analytical precision	43
13.5.3	Overall bias of sampling and analysis methods	44
13.5.4	Overall precision of sampling and analysis methods	44
13.6	Overall uncertainty of sampling and analysis methods	44
13.7	Effects on sampler performance	45
13.7.1	Effect of exposure concentration and time on sampler performance	45
13.7.2	Effect of atmospheric temperature, pressure and humidity on sampler performance	45
13.7.3	Effect of air velocity on performance of diffusive badges	45
13.8	Sample uptake rate and sampling capacity of diffusive badges	46
13.9	Collection efficiency, breakthrough volume and sampling capacity of sorbent tubes	46
13.10	Storage stability	46
13.11	Mechanical strength	46
13.12	Interferences	46
14	Test report	47
14.1	Test record	47
14.2	Laboratory report	48
Annex A (informative) Guidance on selection of a sampling method for mercury vapour		49
Annex B (informative) Temperature and pressure corrections		50
Bibliography		52