

# DIN EN 17199-3:2019-12 (E)

## Workplace exposure - Measurement of dustiness of bulk materials that contain or release respirable NOAA or other respirable particles - Part 3: Continuous drop method

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	6
4	Symbols and abbreviations .....	6
5	Principle .....	6
6	Equipment .....	8
6.1	General .....	8
6.2	Test apparatus .....	9
7	Requirements .....	11
7.1	General .....	11
7.2	Engineering control measures .....	11
7.3	Conditioning of the test material .....	11
7.4	Conditioning of the test equipment .....	12
8	Preparation .....	12
8.1	Test sample .....	12
8.2	Moisture content of the test material .....	12
8.3	Bulk density of the test material .....	12
8.4	Sampling for analytical or imaging purposes .....	12
8.5	Preparation of test apparatus .....	12
9	Test procedure .....	13
10	Evaluation of data .....	15
10.1	Respirable dustiness mass fraction .....	15
10.2	Number-based dustiness index .....	15
10.3	Number-based emission rate .....	16
10.4	Additional results of the tests .....	16
10.5	Morphology and chemical characterization of the particles .....	16
11	Test report .....	17
Annex A (informative) Description and characteristic properties of the continuous drop method .....		18
A.1	General .....	18
A.2	Energy input and dust developing procedure .....	18
A.3	Analytical methods and results .....	19
Annex B (informative) Illustration of an experimental CDD set-up example .....		20
Bibliography .....		24