

ISO 24095:2021-09 (E)

Workplace air - Guidance for the measurement of respirable crystalline silica

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Analytical quality requirements	3
6	Administrative controls	3
7	Sampling	4
7.1	General	4
7.2	Sampler	4
7.3	Filters and foams	4
7.4	Sampling flow measurement devices and pumps	5
7.5	Sampling period	5
7.6	Transportation	6
8	Procedures	7
8.1	Handling of filter cassettes	7
8.2	Method validation	7
8.3	Calibration	7
8.4	Sample preparation	8
8.5	Sample measurement	9
8.5.1	Limit of Detection	9
8.5.2	X-ray diffraction	9
8.5.3	Infrared analysis	9
8.6	Instrumental variation	10
8.6.1	X-ray diffraction	10
8.6.2	Infrared analysis	10
9	Internal quality control	10
10	External verification and assessment of uncertainty	11
11	Test report	11
11.1	Minimum report requirements	11
11.2	Data to be archived by the laboratory	12
Annex A (informative) Polymorphs of crystalline silica and their interferences		13
Annex B (informative) The quantification of cristobalite using X-ray diffraction		19
Annex C (informative) Example of quality control charting for respirable crystalline silica		23

Annex D (informative) Estimation of expanded uncertainty for measurements of respirable crystalline silica	25
Annex E (informative) Differences between samplers (cyclones and other types)	35
Annex F (informative) Use of proficiency test data to evaluate the performance of XRD and IR methods in the presence of interferences	37
Bibliography	42