

# ISO 21438-1:2022-05 (E)

## Workplace atmospheres - Determination of inorganic acids by ion chromatography - Part 1: Non-volatile acids (sulfuric acid and phosphoric acid)

---

Contents	Page
Foreword.....	v
Introduction.....	vi
<b>1 Scope.....</b>	<b>1</b>
<b>2 Normative references.....</b>	<b>1</b>
<b>3 Terms and definitions.....</b>	<b>2</b>
<b>4 Principle.....</b>	<b>3</b>
<b>5 Requirement.....</b>	<b>3</b>
<b>6 Reagents.....</b>	<b>3</b>
<b>7 Apparatus.....</b>	<b>4</b>
7.1 Sampling equipment.....	4
7.2 Laboratory apparatus.....	6
<b>8 Occupational exposure assessment.....</b>	<b>7</b>
<b>9 Sampling.....</b>	<b>7</b>
9.1 Preliminary considerations.....	7
9.1.1 Selection and use of samplers.....	7
9.1.2 Sampling period.....	7
9.1.3 Effect of temperature and pressure on flow rate measurements.....	7
9.1.4 Sample handling.....	8
9.1.5 Sampling interferences.....	8
9.2 Preparation for sampling.....	8
9.2.1 Cleaning of samplers.....	8
9.2.2 Loading the samplers with filters.....	9
9.2.3 Setting the volumetric flow rate.....	9
9.2.4 Field blanks.....	9
9.3 Sampling position.....	9
9.3.1 Personal sampling.....	9
9.3.2 Static sampling.....	9
9.4 Collection of samples.....	9
9.5 Transportation.....	10
9.5.1 Samplers that collect airborne particles on the filter.....	10
9.5.2 Samplers with an internal filter cassette.....	10
9.5.3 Samplers of the disposable cassette type.....	10
9.5.4 Transport of samples to the laboratory.....	11
<b>10 Analysis.....</b>	<b>11</b>
10.1 Preparation of test, calibration solutions and filter samples.....	11
10.1.1 General.....	11
10.1.2 Quartz fibre filters.....	11
10.1.3 PVC and PTFE filters.....	11
10.1.4 Preparation of calibration solutions.....	12
10.2 Instrumental analysis.....	12
10.3 Estimation of detection and quantification limits.....	13
10.3.1 Estimation of the instrumental detection limits.....	13
10.3.2 Estimation of the method detection limit and quantification limit.....	13
10.4 Quality control.....	13
10.4.1 Reagent blanks and laboratory blanks.....	13

10.4.2	Quality control solutions.....	14
10.4.3	Certified reference materials.....	14
10.4.4	External quality assessment.....	14
10.5	Measurement uncertainty.....	14
<b>11</b>	<b>Expression of results.....</b>	<b>15</b>
<b>12</b>	<b>Method performance.....</b>	<b>15</b>
12.1	Sample collection and stability.....	15
12.2	Quantification limits.....	15
12.3	Upper limits of the analytical range.....	15
12.4	Bias and precision.....	16
12.4.1	Analytical bias.....	16
12.4.2	Analytical precision.....	16
12.5	Uncertainty of sampling and analysis method.....	16
12.6	Interferences.....	16
<b>13</b>	<b>Test report.....</b>	<b>17</b>
13.1	Test record.....	17
13.2	Laboratory report.....	18
	<b>Annex A (informative) Temperature and pressure correction.....</b>	<b>19</b>
	<b>Bibliography.....</b>	<b>21</b>