

DIN EN 15051-3:2026-01 (E)

Workplace exposure - Measurement of the dustiness of bulk materials - Part 3: Continuous drop method

| Contents | | Page |
|-------------------------|--|-------------|
| European foreword | | 3 |
| Introduction | | 4 |
| 1 | Scope | 5 |
| 2 | Normative references | 5 |
| 3 | Terms and definitions | 6 |
| 4 | Requirements | 6 |
| 4.1 | General | 6 |
| 4.2 | Conditioning of the bulk material | 6 |
| 4.2.1 | As-received condition | 6 |
| 4.2.2 | Conditioning specifications | 6 |
| 4.3 | Sample and environmental control | 6 |
| 4.4 | Moisture content | 6 |
| 4.5 | Bulk density | 7 |
| 4.6 | Test procedure | 7 |
| 4.7 | Replicate tests | 7 |
| 4.8 | In-house / test powder | 7 |
| 4.9 | Reporting | 7 |
| 5 | Continuous drop method | 7 |
| 5.1 | Description of test apparatus | 7 |
| 5.2 | Filters | 9 |
| 5.3 | Ancillary equipment | 9 |
| 5.4 | Preparation of test sample | 9 |
| 5.5 | Preparation of test apparatus | 10 |
| 5.6 | Test procedure | 10 |
| 5.7 | Weighing the filters | 10 |
| 5.8 | Limit of detection (LOD) and limit of quantification (LOQ) | 11 |
| 5.9 | Determination of the inhalable and respirable dustiness mass fractions | 12 |
| 6 | Evaluation of dustiness | 13 |
| 7 | Test report | 13 |
| Bibliography | | 15 |