

# DIN EN 15051-3:2026-01 (E)

## Workplace exposure - Measurement of the dustiness of bulk materials - Part 3: Continuous drop method

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
Introduction .....		4
1	Scope .....	5
2	Normative references .....	5
3	Terms and definitions .....	6
4	Requirements .....	6
4.1	General .....	6
4.2	Conditioning of the bulk material .....	6
4.2.1	As-received condition .....	6
4.2.2	Conditioning specifications .....	6
4.3	Sample and environmental control .....	6
4.4	Moisture content .....	6
4.5	Bulk density .....	7
4.6	Test procedure .....	7
4.7	Replicate tests .....	7
4.8	In-house / test powder .....	7
4.9	Reporting .....	7
5	Continuous drop method .....	7
5.1	Description of test apparatus .....	7
5.2	Filters .....	9
5.3	Ancillary equipment .....	9
5.4	Preparation of test sample .....	9
5.5	Preparation of test apparatus .....	10
5.6	Test procedure .....	10
5.7	Weighing the filters .....	10
5.8	Limit of detection (LOD) and limit of quantification (LOQ) .....	11
5.9	Determination of the inhalable and respirable dustiness mass fractions .....	12
6	Evaluation of dustiness .....	13
7	Test report .....	13
Bibliography .....		15