

ISO 6868:2026-08 (E)

Workplace air - Quantitative determination of quartz and cristobalite in bulk materials by X-ray powder diffraction methods

Contents	Page
Foreword	v
Introduction	vi
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	2
5 Equipment	3
5.1 Diffraction system	3
5.1.1 Diffractometer	3
5.1.2 Specimen holders	3
5.2 Balance	3
5.3 Reference materials	3
5.3.1 Quartz and cristobalite	3
5.3.2 Internal standard	4
5.3.3 XRD drift correction disc	4
5.4 Equipment for the preparation of specimens of infinite thickness	4
5.4.1 Laboratory drying oven	4
5.4.2 Masonry hammer, jaw crusher or similar device	4
5.4.3 Laboratory mill	4
5.4.4 Other equipment	5
5.5 Equipment for the preparation of thin thickness specimens	5
5.5.1 Filters for analysis	5
5.5.2 Other equipment	6
5.6 Equipment for sample treatment and reagents	7
5.6.1 Furnace	7
5.6.2 Reagents	7
6 Sampling	8
7 Specimen preparation	8
7.1 General	8
7.2 Crushing	10
7.3 Grinding	10
7.4 Drying	12
7.5 Pre-concentration and removal of interfering phases	12
7.6 Weighing and mounting of a specimen of infinite thickness	12
7.7 Weighing and deposition of thin layer specimen on filter	14
8 Analysis	15
8.1 Symbols	15
8.2 Parameters of a diffraction line profile	15
8.3 Instrument conditions	16
8.4 Analytical methods	17
8.4.1 Choice of the analytical method	17
8.4.2 Calibration specimens, reference diffraction patterns and reference values	17

8.4.3	Quartz and cristobalite identification: Preliminary qualitative analysis	18
8.4.4	Quantitative analysis by the external standard method	19
8.4.5	Quantitative analysis by the internal standard method	21
8.4.6	Quantitative analysis by the spiking method	24
9	Performance characteristics of the methods	25
9.1	Limits of detection and quantification	25
9.2	Uncertainty of measurement	26
9.3	Equivalency of the methods and between laboratory precision	26
10	Test report	26
10.1	Minimum report requirements	26
10.2	Data to be archived by the laboratory	27
Annex A (informative) Expected line positions and relative intensities of quartz and cristobalite		28
Annex B (informative) Interferences on quartz and cristobalite diffraction patterns		30
Annex C (informative) Sample treatment strategies		34
Annex D (informative) Examples of analyses		36
Annex E (informative) Examples of equivalency of the methods and between laboratory precision .		51
Bibliography		53