

ISO 15202-2:2001-07 (E)

Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 2: Sample preparation

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	2
3 Terms and definitions	2
4 Principle	3
5 Requirements	4
6 Reactions	4
7 Reagents	4
8 Laboratory apparatus	4
9 Procedure	5
9.1 Soluble metal and metalloid compounds	5
9.2 Total metals and metalloids and their compounds	5
9.3 Mixed exposure	5
10 Special cases	6
10.1 Action to be taken if there is doubt about the effectiveness of the selected sample dissolution method	6
10.2 Action to be taken when particles have become dislodged from the filter during transportation	6
11 Laboratory records	6
Annex A (informative) Safety precautions to be observed when using hydrofluoric and perchloric acids	7
Annex B (normative) Sample dissolution method for soluble metal and metalloid compounds	8
Annex C (normative) Sample dissolution using nitric acid and hydrochloric acid on a hotplate	14
Annex D (normative) Sample dissolution using hydrofluoric and nitric acids and ultrasonic agitation	17
Annex E (normative) Sample dissolution based on the use of sulfuric acid and hydrogen peroxide on a hotplate	20
Annex F (normative) Sample dissolution based on the use of nitric acid and perchloric acid on a hotplate	24

Annex G (normative) Sample dissolution in a closed vessel microwave digestion system	28
Annex H (normative) Action to be taken when there is visible, undissolved, particulate material after sample dissolution	33
Bibliography	37