

# ISO 15202-3:2004-11 (E)

## Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 3: Analysis

---

<b>Contents</b>	<b>Page</b>
Foreword .....	iv
Introduction .....	v
1 Scope .....	1
2 Normative references .....	2
3 Terms, definitions and abbreviated terms .....	2
3.1 General definitions .....	2
3.2 Analytical definitions .....	3
3.3 ICP-AES definitions .....	4
3.4 Statistical terms .....	7
4 Principle .....	8
5 Requirements .....	8
6 Reagents .....	8
7 Laboratory apparatus .....	12
8 Procedure .....	13
8.1 Method development .....	13
8.2 Instrument performance checks .....	18
8.3 Routine analysis .....	18
8.4 Estimation of detection and quantification limits .....	19
8.5 Quality control .....	20
8.6 Measurement uncertainty .....	21
9 Expression of results .....	21
10 Method performance .....	22
10.1 Method detection limits and quantification limits .....	22
10.2 Upper limits of the analytical range .....	23
10.3 Bias and precision .....	23
10.4 Overall uncertainty of sampling and analysis methods .....	23
10.5 Spectral interferences .....	24
11 Test report .....	24
11.1 Test records .....	24
11.2 Laboratory report .....	25
Annex A (informative) Guidance on maintenance of ICP-AES instrumentation .....	26
Annex B (informative) Examples of performance checks and fault diagnostics .....	28
Annex C (informative) Procedure for quality control and identification (QUID) of malfunctions of inductively coupled plasma atomic emission spectrometers .....	29
Annex D (informative) Recalculation of metal and metalloid in air concentrations to reference conditions .....	35
Bibliography .....	36