

ISO 16740:2005-02 (E)

**Workplace air - Determination of hexavalent chromium in airborne particulate matter
- Method by ion chromatography and spectrophotometric measurement using
diphenyl carbazide**

Contents

	Page
Foreword	v
Introduction	vi
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
3.1 General definitions	2
3.2 Particle size fraction definitions	3
3.3 Sampling definitions	3
3.4 Analytical definitions	4
3.5 Statistical terms	5
4 Principle	6
5 Reactions	7
6 Requirement	7
7 Reagents	7
8 Apparatus	10
8.1 Sampling equipment	10
8.2 Laboratory apparatus	12
9 Occupational exposure assessment	15
9.1 General	15
9.2 Personal sampling	15
9.3 Static sampling	16
9.4 Selection of measurement conditions and measurement pattern	16
10 Sampling method	17
10.1 Preliminary considerations	17
10.2 Preparation for sampling	18
10.3 Sampling position	19
10.4 Collection of samples	19
10.5 Transportation	20
11 Analysis	21
11.1 Analytical requirements	21
11.2 Preparation of solutions for determination of soluble hexavalent chromium compounds ..	22
11.3 Preparation of solutions for determination of insoluble hexavalent chromium compounds ..	23
11.4 Instrumental analysis	25
11.5 Estimation of detection and quantification limits	27
11.6 Quality control	27
11.7 Measurement uncertainty	28

12	Expression of results	28
13	Method performance	29
13.1	Sample collection and stability	29
13.2	Hotplate extraction	29
13.3	Ultrasonic extraction	29
13.4	Interferences	29
14	Special cases	30
14.1	Spray-painting	30
14.2	Action to be taken when particles have become dislodged from the filter during transportation	30
15	Test report	30
15.1	Test record	30
15.2	Laboratory report	31
	Annex A (informative) Temperature and pressure corrections	32
	Annex B (informative) Background on methods for determination of hexavalent chromium in air and guidance on their use	34
	Bibliography	38