

# ISO 7066-2:1988-07 (E)

## Assessment of uncertainty in the calibration and use of flow measurements devices; part 2: non-linear calibration relationships

---

<b>Contents</b>		<b>Page</b>
<b>0</b>	<b>Introduction.....</b>	<b>1</b>
<b>1</b>	<b>Scope and field of application .....</b>	<b>1</b>
<b>2</b>	<b>References .....</b>	<b>1</b>
<b>3</b>	<b>Definitions .....</b>	<b>1</b>
<b>4</b>	<b>Symbols and abbreviations.....</b>	<b>1</b>
<b>5</b>	<b>Curve fitting .....</b>	<b>2</b>
<b>5.1</b>	<b>General .....</b>	<b>2</b>
<b>5.2</b>	<b>Computational methods .....</b>	<b>3</b>
<b>5.3</b>	<b>Selecting the Optimum degree of fit.....</b>	<b>3</b>
<b>6</b>	<b>Uncertainty.....</b>	<b>4</b>
<b>Annexes</b>		
<b>A</b>	<b>Regression methods .....</b>	<b>5</b>
<b>B</b>	<b>Orthogonal polynomial curve fitting.....</b>	<b>9</b>
<b>C</b>	<b>Computer program using orthogonal polynomials.....</b>	<b>11</b>
<b>D</b>	<b>Examples .....</b>	<b>17</b>
<b>E</b>	<b>Finite-difference method .....</b>	<b>27</b>