

# ISO 29864:2007-12 (E)

Self adhesive tapes — Measurement of breaking strength and elongation at break

---

## Contents

	page
Foreword.....	3
Introduction .....	4
1 Scope .....	5
2 Terms and definitions.....	5
3 Significance and use .....	5
4 Principle .....	5
5 Apparatus .....	6
6 Test sample and test pieces .....	7
7 Procedure .....	7
8 Expression of results .....	8
9 Test report .....	8