

# ISO 13165-3:2024-12 (E)

## Water quality - Radium-226 - Part 3: Test method using coprecipitation and gamma-ray spectrometry

---

### Contents

Page

Foreword.....	iv
Introduction.....	v
<b>1 Scope.....</b>	<b>1</b>
<b>2 Normative references.....</b>	<b>1</b>
<b>3 Terms and definitions.....</b>	<b>2</b>
<b>4 Symbols.....</b>	<b>2</b>
<b>5 Principle.....</b>	<b>3</b>
<b>6 Reagents and equipment.....</b>	<b>4</b>
6.1 Reagents.....	4
6.2 Equipment.....	4
<b>7 Sampling.....</b>	<b>5</b>
7.1 General.....	5
7.2 Sample collection.....	5
7.3 Sample transportation and storage.....	5
<b>8 Procedure.....</b>	<b>5</b>
8.1 Blank sample preparation.....	5
8.2 Sample preparation.....	5
8.3 Counting procedure.....	6
<b>9 Quality assurance and quality control programme.....</b>	<b>6</b>
9.1 General.....	6
9.2 Interferences.....	6
9.3 Method verification.....	7
9.4 Demonstration of analyst capability.....	7
<b>10 Expression of results.....</b>	<b>7</b>
10.1 General.....	7
10.2 Water-soluble <sup>226</sup> Ra activity concentration.....	7
10.3 Standard uncertainty of activity concentration.....	8
10.4 Decision threshold.....	8
10.5 Detection limit.....	9
10.6 Limits of the coverage intervals.....	9
10.6.1 Limits of the probabilistically symmetric coverage interval.....	9
10.6.2 Shortest coverage interval.....	10
10.7 Corrections for contributions from other radionuclides and background.....	10
10.7.1 General.....	10
10.7.2 Contribution from other radionuclides.....	10
10.7.3 Contribution from background.....	11
<b>11 Test report.....</b>	<b>12</b>
<b>Annex A (informative) Uranium-238 decay chain.....</b>	<b>14</b>
<b>Bibliography.....</b>	<b>15</b>