

ISO 3548-2:2020 (E)

Plain bearings — Thin-walled half bearings with or without flange — Part 2: Measurement of wall thickness and flange thickness

Contents

| | |
|-----|--|
| | Foreword |
| 1 | Scope |
| 2 | Normative references |
| 3 | Terms and definition |
| 4 | Symbols and units |
| 5 | Purpose of checking |
| 6 | Checking methods |
| 6.1 | Measuring principle of wall thickness |
| 6.2 | Line measurement around the circumference |
| 6.3 | Line measurement in axial direction |
| 6.4 | Point measurement |
| 6.5 | Grading of bearings |
| 6.6 | Eccentric bore |
| 6.7 | Measuring principle for flange thickness |
| 6.8 | Measuring point for flange thickness |
| 7 | Requirements for measuring equipment and specimen for the contact method |
| 7.1 | Tip-radius for measuring pin on the outside surface |
| 7.2 | Tip-radius for measuring pin on the inside surface |
| 7.3 | Measuring pin load |
| 7.4 | Set-up |
| 7.5 | Periodical control |
| 7.6 | Measurement failures on the inside and/or outside surface |
| 8 | Checking of measuring equipment |

Page count: 10