

# ISO 3547-2:2006-10 (E)

## Plain bearings - Wrapped bushes - Part 2: Test data for outside and inside diameters

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Symbols and units .....</b>	<b>2</b>
<b>5</b>	<b>Presentation of data on drawing .....</b>	<b>2</b>
<b>6</b>	<b>Tests .....</b>	<b>4</b>
<b>6.1</b>	<b>Test A .....</b>	<b>4</b>
<b>6.2</b>	<b>Test B .....</b>	<b>4</b>
<b>6.3</b>	<b>Test C .....</b>	<b>4</b>
<b>6.4</b>	<b>Test D .....</b>	<b>4</b>
<b>7</b>	<b>Test A .....</b>	<b>4</b>
<b>7.1</b>	<b>Description .....</b>	<b>4</b>
<b>7.2</b>	<b>Calculation basis .....</b>	<b>4</b>
<b>7.3</b>	<b>Obtaining data -- Example .....</b>	<b>7</b>
<b>7.4</b>	<b>Presentation of data on drawing -- Example .....</b>	<b>8</b>
<b>8</b>	<b>Test B .....</b>	<b>8</b>
<b>8.1</b>	<b>Description .....</b>	<b>8</b>
<b>8.2</b>	<b>Obtaining data -- Example .....</b>	<b>9</b>
<b>8.3</b>	<b>Presentation of data on drawing -- Example .....</b>	<b>9</b>
<b>9</b>	<b>Test C .....</b>	<b>9</b>
<b>9.1</b>	<b>Description .....</b>	<b>9</b>
<b>9.2</b>	<b>Obtaining data -- Example .....</b>	<b>10</b>
<b>9.3</b>	<b>Presentation of data on drawing -- Example .....</b>	<b>11</b>
<b>10</b>	<b>Test D .....</b>	<b>11</b>
<b>10.1</b>	<b>Description .....</b>	<b>11</b>
<b>10.2</b>	<b>Obtaining data -- Example .....</b>	<b>11</b>
<b>10.3</b>	<b>Presentation of data on drawing -- Example .....</b>	<b>12</b>