

# DIN 22102-3:2020-12 (E)

## Conveyor belts with textile plies for bulk goods - Part 3: Permanent joints

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
<b>1</b>	<b>Scope .....</b>	<b>4</b>
<b>2</b>	<b>Normative references .....</b>	<b>4</b>
<b>3</b>	<b>Terms, definitions and symbols .....</b>	<b>4</b>
<b>4</b>	<b>Dimensions, design and designation .....</b>	<b>4</b>
<b>4.1</b>	<b>General .....</b>	<b>4</b>
<b>4.2</b>	<b>Splices for conveyor belts with one textile ply, for belt types 500/1 .....</b>	<b>5</b>
<b>4.3</b>	<b>Splices for conveyor belts with one ply (finger splice), for belt types 630/1 .....</b>	<b>6</b>
<b>4.4</b>	<b>Splices for conveyor belts with two plies and intermediate tension member .....</b>	<b>7</b>
<b>4.5</b>	<b>Splices for conveyor belts with two or more plies and bonding layers .....</b>	<b>8</b>
<b>5</b>	<b>Splicing conveyor belts .....</b>	<b>12</b>
<b>5.1</b>	<b>General .....</b>	<b>12</b>
<b>5.2</b>	<b>Hot plates in vulcanizing machines .....</b>	<b>12</b>
<b>6</b>	<b>Electrical and flammability safety requirements .....</b>	<b>12</b>
<b>7</b>	<b>Marking .....</b>	<b>12</b>
<b>Figures</b>	<b>Figure 1 -- Overlapping splice .....</b>	<b>5</b>
	<b>Figure 2 -- Finger splice .....</b>	<b>6</b>
	<b>Figure 3 -- Splice with intermediate tension member .....</b>	<b>7</b>
	<b>Figure 4 -- Stepped splice .....</b>	<b>8</b>
	<b>Figure 5 -- Conveyor belt with two plies: 1-step splice .....</b>	<b>9</b>
	<b>Figure 6 -- Conveyor belt with two plies: 2-step splice .....</b>	<b>9</b>
	<b>Figure 7 -- Conveyor belt with three plies: 2-step splice .....</b>	<b>9</b>
	<b>Figure 8 -- Conveyor belt with four plies: 3-step splice .....</b>	<b>10</b>
	<b>Figure 9 -- Conveyor belt with five plies: 4-step splice .....</b>	<b>10</b>
<b>Tables</b>	<b>Table 1 -- Loss in breaking strength .....</b>	<b>5</b>
	<b>Table 2 -- Minimum step lengths and splice lengths for overlapping splices .....</b>	<b>5</b>
	<b>Table 3 -- Finger splice dimensions .....</b>	<b>6</b>
	<b>Table 4 -- Minimum steps and splice lengths for splices with intermediate tension member .....</b>	<b>8</b>
	<b>Table 5 -- Minimum steps and splice lengths for conveyor belts with two plies .....</b>	<b>11</b>
	<b>Table 6 -- Minimum steps and splice lengths for conveyor belts with more than two plies .....</b>	<b>11</b>