

ISO/IEC 29121:2009-02 (E)

Information technology - Digitally recorded media for information interchange and storage - Data migration method for DVD-R, DVD-RW, DVD-RAM, +R, and +RW disks

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Test methods	3
4.1	Test parameters	3
4.2	Test Drive	3
4.2.1	Test drive calibration	3
4.2.2	Test preparation	4
4.2.3	Test execution	4
4.3	Test area	4
5	Test result evaluation	4
5.1	Initial performance test result evaluation	4
5.2	Periodical performance test result evaluation	5
6	Test frequency	6
7	Prevention of deterioration	6
Annex A (informative) Causes of deterioration for DVD-R, DVD-RW, DVD-RAM, +R, and +RW disks ...		7
A.1	Deterioration	7
A.2	Disk structure	7
A.3	Causes of deterioration	7
A.4	Nature of deterioration	8
A.5	Effects of deterioration	8
Annex B (informative) Recommendations on handling, storage and cleaning conditions for DVD-R, DVD-RW, DVD-RAM, +R, and +RW disks		9
B.1	Handling	9
B.2	Storage	9
B.3	Cleaning	10
Annex C (informative) Relation between BER and PIE SUM 8		11
Annex D (informative) Normalization of the time scales		12
Annex E (informative) Test area		14
Bibliography		15