

## **Contents**

	<b>Foreword</b>
	<b>Introduction</b>
<b>1</b>	<b>Scope</b>
<b>2</b>	<b>Normative references</b>
<b>3</b>	<b>Terms and definitions</b>
<b>4</b>	<b>Test equipment</b>
<b>5</b>	<b>Cutting attachment</b>
<b>5.1</b>	<b>Guide bar</b>
<b>5.2</b>	<b>Chain speed</b>
<b>5.3</b>	<b>Saw chain</b>
<b>6</b>	<b>Test samples and pre-conditioning</b>
<b>6.1</b>	<b>Test samples</b>
<b>6.2</b>	<b>Test temperature</b>
<b>7</b>	<b>Pre-calibration of test arrangement</b>
<b>8</b>	<b>Set up of window test sample in test rig</b>
<b>9</b>	<b>Test procedure</b>
<b>10</b>	<b>Total number of test runs</b>
<b>11</b>	<b>Performance requirements</b>
<b>12</b>	<b>Labelling</b>
<b>13</b>	<b>Test report</b>
<b>Annex A</b>	<b>(normative) Saw chain stopping device</b>