

E DIN EN 4533-001:2024-06 (E)

Erscheinungsdatum: 2024-04-26

Aerospace series - Fibre optic systems - Handbook - Part 001: Termination methods and tools; English version prEN 4533-001:2024

Contents		Page
European foreword		4
Introduction.....		5
1	Scope.....	6
1.1	General.....	6
1.2	Need for high-integrity terminations	6
2	Normative references.....	7
3	Terms and definitions.....	7
4	Component selection	7
4.1	Elements.....	7
4.2	Fibre optic cables	7
4.2.1	General.....	7
4.2.2	Cable construction.....	8
4.2.3	Fibre choice.....	9
4.2.4	Cladding materials	11
4.3	Primary buffer materials	11
4.3.1	Function.....	11
4.3.2	Acrylate.....	12
4.3.3	Polyimide.....	12
4.3.4	Silicone.....	12
4.3.5	Strength members	12
4.4	Outer jacket.....	13
4.5	Fibre optic interconnects (connectors).....	13
4.5.1	Introduction.....	13
4.5.2	The optical interface.....	14
4.5.3	Single-way interconnects/connectors	20
4.5.4	Multi-way interconnects/connectors	20
4.5.5	Choice of tooling.....	21
5	Health and safety aspects.....	22
5.1	General.....	22
5.2	Chemicals.....	22
5.3	Sharps.....	23
6	Termination process	23
6.1	Objective	23
6.2	Cable preparation	24
6.2.1	General.....	24
6.2.2	Cutting to length.....	24
6.2.3	Removal of outer jacket.....	25
6.2.4	Cable handling tools (gripping the cable).....	30
6.2.5	Strength member trimming/removal	31
6.3	Removal of secondary coating(s).....	32
6.4	Removal of primary coatings.....	32
6.4.1	General.....	32
6.4.2	Mechanical techniques for primary coating removal.....	33

6.4.3	Alternative techniques.....	39
6.4.4	Troublesome coatings — Polyimide and Silicone.....	40
6.4.5	Evidence of strength reduction when stripping primary buffer coatings.....	42
6.4.6	To clean or not to clean	43
6.5	Adhesives.....	44
6.5.1	General	44
6.5.2	Adhesive types.....	44
6.5.3	The importance of glass transition temperature (T_g)	46
6.5.4	Epoxy cure schedule	48
6.5.5	Usability	50
6.5.6	Qualification	54
6.6	Connector preparation	54
6.6.1	Dry fitting	54
6.7	Attachment of fibre to the terminus	56
6.7.1	Application of adhesive	56
6.7.2	Inserting fibre ‘best-practice’.....	59
6.8	Adhesive cure.....	63
6.8.1	General	63
6.8.2	Orientation.....	63
6.8.3	Curing equipment.....	63
6.9	Excess fibre removal.....	67
6.9.1	General	67
6.9.2	Post-cure rough cleaving	67
6.9.3	Pre-cleave.....	69
6.9.4	Safety.....	69
6.9.5	Cleaving tools	69
6.9.6	Sprung blade hand tools.....	70
6.9.7	Cleaving fibres in multi-fibre ferrules	71
6.10	Polishing	71
6.10.1	Rationale.....	71
6.10.2	Performance metrics.....	71
6.10.3	End-face geometries	71
6.10.4	End-face geometry parameters	72
6.10.5	Polishing stages.....	81
6.10.6	Methods for controlling end-face geometry	95
7	Beginning of life inspection	101
7.1	General	101
7.2	Optical or visual inspection	101
7.3	Interferometric inspection	103
7.3.1	General	103
7.3.2	Inspection and pass/fail criteria.....	105
	Bibliography	108