

DIN EN 16602-70-08:2015-05 (E)

Space product assurance - Manual soldering of high-reliability electrical connections; English version EN 16602-70-08:2015

Foreword	9
Introduction	10
1 Scope	11
2 Normative references	12
3 Terms, definitions and abbreviated terms	13
3.1 Terms from other standards.....	13
3.2 Terms specific to the present standard	13
3.3 Abbreviated terms.....	20
4 Principles of reliable soldered connections	22
5 Preparatory conditions	23
5.1 Calibration	23
5.2 Facility cleanliness.....	23
5.3 Environmental conditions.....	23
5.4 Lighting requirements	24
5.5 Precautions against static discharges	24
5.5.1 General.....	24
5.5.2 Precautions against ESD during manufacturing	24
5.5.3 Protective Packaging and ESD Protection	25
5.5.4 Packing and filler materials	26
5.6 Equipment and tools	26
5.6.1 General.....	26
5.6.2 Brushes.....	26
5.6.3 Cutters and pliers.....	26
5.6.4 Bending tools	27
5.6.5 Clinching tools.....	27
5.6.6 Insulation strippers.....	28
5.6.7 Soldering irons and resistance soldering equipment	29
5.6.8 Soldering tools	30

6 Materials selection	31
6.1 General.....	31
6.2 Solder	31
6.2.1 Form	31
6.2.2 Composition	31
6.3 Flux	32
6.3.1 Rosin-based fluxes.....	32
6.3.2 INH1 corrosive acid flux	33
6.3.3 Application of flux.....	33
6.4 Solvents.....	34
6.5 Flexible insulation materials.....	34
6.6 Terminals.....	35
6.6.1 Materials	35
6.6.2 Tin-, silver- and gold-plated terminals.....	35
6.6.3 Shape of terminals	35
6.7 Wires	35
6.8 PCBs	36
6.8.1 Boards	36
6.8.2 Gold finish on conductors.....	36
6.9 Component lead finishes	36
6.10 Adhesives (staking compounds and heat sinking), encapsulants and conformal coatings.....	36
7 Preparation for soldering.....	38
7.1 General.....	38
7.1.1 Tools.....	38
7.1.2 Components.....	38
7.2 Preparation of conductors, terminals and solder cups.....	38
7.2.1 Insulation removal.....	38
7.2.2 Surfaces to be soldered	39
7.2.3 De-golding of gold-plated leads and terminals.....	40
7.2.4 Constraints on degolding and pretinning methods.....	41
7.2.5 Pretinning of stranded wires.....	42
7.2.6 Pre-tinning of component leads and solid-wire conductors.....	42
7.3 Preparation of the soldering bit.....	43
7.3.1 Fit.....	43
7.3.2 Maintenance	43
7.3.3 Plated bits	43

7.3.4	Tip in operation	43
7.4	Maintenance of resistance-type soldering electrodes.....	44
7.5	Handling (work station).....	44
7.6	Storage (work station).....	44
7.6.1	Components.....	44
7.6.2	PCBs.....	44
7.6.3	Materials requiring segregation	44
7.7	Preparation of PCBs for soldering.....	45
7.7.1	Process.....	45
7.7.2	Demoisturization methods.....	45
7.7.3	Storage of prepared PCBs	45
8	Mounting of components.....	46
8.1	General requirements	46
8.1.1	Introduction	46
8.1.2	Heavy components	46
8.1.3	Metal-case components	46
8.1.4	Glass-encased components.....	47
8.1.5	Stress relief of components with bendable leads.....	47
8.1.6	Stress relief of components with non-bendable leads.....	48
8.1.7	Reinforced plated-through holes	50
8.1.8	Lead and conductor cutting	50
8.1.9	Solid hook-up wire.....	50
8.1.10	Location	50
8.1.11	Conformal coating, cementing and encapsulation	50
8.2	Lead bending requirements	51
8.2.1	General.....	51
8.2.2	Conductors terminating on both sides of a non-plated-through hole.....	51
8.3	Mounting of terminals to PCBs.....	52
8.4	Lead attachment to PCBs	53
8.4.1	General	53
8.4.2	Clinched leads	53
8.4.3	Stud leads.....	55
8.4.4	Lapped round leads	56
8.4.5	Lapped ribbon leads.....	56
8.5	Mounting of components to terminals	56
8.6	Mounting of connectors to PCBs.....	58
9	Attachment of conductors to terminals, solder cups and cables	59

9.1	General.....	59
9.1.1	Conductors	59
9.1.2	Terminals	59
9.2	Wire termination	59
9.2.1	Breakouts from cables	59
9.2.2	Insulation clearance	59
9.2.3	Solid hook-up wire.....	60
9.2.4	Stress relief.....	60
9.3	Turret and straight-pin terminals	60
9.3.1	Side route	60
9.3.2	Bottom route	60
9.4	Bifurcated terminals	61
9.4.1	General	61
9.4.2	Bottom route	61
9.4.3	Side route	62
9.4.4	Top route	63
9.4.5	Combination of top and bottom routes.....	64
9.4.6	Combination of side and bottom routes	64
9.5	Hook terminals.....	64
9.6	Pierced terminals.....	65
9.7	Solder cups (connector type)	66
9.8	Insulation sleeving	66
9.9	Wire and cable interconnections	67
9.9.1	General	67
9.9.2	Preparation of wires	67
9.9.3	Preparation of shielded wires and cables	67
9.9.4	Pre-assembly	68
9.9.5	Soldering procedures	68
9.9.6	Cleaning.....	69
9.9.7	Inspection	69
9.9.8	Workmanship	69
9.9.9	Sleeving of interconnections	69
9.10	Connection of stranded wires to PCBs.....	70
10	Soldering to terminals and PCBs	72
10.1	General.....	72
10.1.1	Securing conductors	72
10.1.2	Thermal shunts	72

10.1.3	High-voltage connections	72
10.2	Solder application to terminals	73
10.2.1	Soldering of swaged terminals onto PCBs	73
10.2.2	Soldering of conductors onto terminals (except cup terminals).....	73
10.2.3	Soldering of conductors onto cup terminals.....	74
10.3	Solder application to PCBs	74
10.3.1	Solder coverage.....	74
10.3.2	Solder fillets	74
10.3.3	Soldering of component leads to plated-through holes.....	74
10.3.4	Solder application	75
10.4	Wicking.....	76
10.5	Solder rework	76
10.6	Repair and modification	76
11	Cleaning of PCB assemblies	77
11.1	General.....	77
11.2	Ultrasonic cleaning	77
11.3	Monitoring for cleanliness	77
11.3.1	Cleanliness testing	77
11.3.2	Testing frequency	78
11.3.3	Test limits.....	78
11.3.4	Test method.....	78
12	Final inspection	79
12.1	General.....	79
12.2	Acceptance criteria	79
12.3	Visual rejection criteria.....	80
13	Verification procedure.....	81
13.1	General.....	81
13.2	Vibration	81
13.3	Temperature cycling	84
13.4	Microsection	84
14	Quality assurance.....	85
14.1	General.....	85
14.2	Data.....	85
14.3	Nonconformance	85
14.4	Calibration	85
14.5	Traceability	86

14.6 Workmanship standards	86
14.7 Inspection	86
14.8 Operator and inspector training and certification	86
15 Workmanship standards	88
15.1 Soldered clinched terminals	88
15.2 Soldered stud terminals	89
15.3 Soldered turret terminals.....	90
15.4 Solder turret terminals	91
15.5 Soldered bifurcated terminals	92
15.6 Soldered hook terminals	93
15.7 Soldered cup terminals	94
15.8 Soldered wire to shielded cable interconnections	95
Annex A (normative) Report on manual soldering of high-reliability electrical connections - DRD.....	98
Annex B (informative) Solder melting temperatures and choice	102
Bibliography.....	103

Figures

Figure 5-1: Profiles of correct and incorrect cutters for trimming leads	27
Figure 5-2 Examples of non-approved types of mechanical strippers	28
Figure 8-1: Assembly of underfilled TO-39 and TO-59, and adhesively staked CKR06	48
Figure 8-2: Methods for incorporating stress relief with components having bendable leads	49
Figure 8-3: Methods for attaching wire extensions to non-bendable leads.....	50
Figure 8-4: Minimum lead bend	51
Figure 8-5: Leads with solder termination on both sides	52
Figure 8-6: Types of terminal swaging	53
Figure 8-7: Clinched-lead terminations - unsupported holes	54
Figure 8-8: Clinched lead terminations - plated through-holes	54
Figure 8-9: Stud terminations	55
Figure 8-10: Methods of through-hole lapped termination.....	57
Figure 8-11: Method of stress relieving parts attached to terminals	57
Figure 9-1: Side- and bottom-route connections to turret terminals	61
Figure 9-2: Bottom-route connections to bifurcated terminal.....	62
Figure 9-3: Side-route connection to bifurcated terminal.....	63
Figure 9-4: Top-route connection to bifurcated terminal.....	64

Figure 9-5: Connections to hook terminals	65
Figure 9-6: Connections to pierced terminals	65
Figure 9-7: Connections to solder cups (connector type).....	66
Figure 9-8: Methods for securing wires.....	69
Figure 9-9: Connection of stranded wires to PCBs	71
Figure 10-1: High voltage connection	73
Figure 10-2: Minimum acceptable wetting on component side.....	75
Figure 15-1: Soldered clinched terminals	88
Figure 15-2: Soldered stud terminals.....	89
Figure 15-3: Soldered turret terminals with twin conductors	90
Figure 15-4: Soldered turret terminals with single conductors.....	91
Figure 15-5: Soldered bifurcated terminals.....	92
Figure 15-6 Soldered hook terminals.....	93
Figure 15-7: Soldered cup terminals.....	94
Figure 15-8: Hand-soldered wire to shielded cable interconnections	95
Figure 15-9: Hand-soldered wire to shielded wire interconnections	96
Figure 15-10: Hand-soldered wire interconnections - details of defects	97

Tables

Table 6-1: Chemical composition of spacecraft solders	32
Table 6-2: Fluxes.....	33
Table 7-1: Clearances for insulation	39
Table 7-2: Solder baths for degolding and pretinning	41
Table 9-1: Dimensions for Figure 9-9	71
Table 13-1: Sine survey.....	82
Table 13-2: Minimum severity for sine vibration testing	83
Table 13-3: Minimum severity for random vibration testing for all applications except launchers	83
Table 13-4: Minimum severity for random vibration testing for launcher	83
Table B-1 : Guide to choice of solder types	102