

# DIN EN 16602-70-13:2015-05 (E)

Space product assurance - Measurements of the peel and pull-off strength of coatings and finishes using pressure-sensitive tapes; English version EN 16602-70-13:2015

---

## Table of contents

<b>Foreword</b> .....	<b>4</b>
<b>1 Scope</b> .....	<b>5</b>
<b>2 Normative references</b> .....	<b>6</b>
<b>3 Terms, definitions and abbreviated terms</b> .....	<b>7</b>
3.1 Terms from other standards.....	7
3.2 Terms specific to the present standard .....	7
3.3 Abbreviated terms.....	7
<b>4 Principles</b> .....	<b>8</b>
<b>5 Requirements</b> .....	<b>10</b>
5.1 Preparatory conditions.....	10
5.1.1 Hazards, health and safety precautions .....	10
5.1.2 Preparation of samples .....	10
5.1.3 Facilities .....	12
5.1.4 Equipment.....	12
5.2 Test procedure .....	14
5.2.1 Preparation .....	14
5.2.2 Peel and pull-off test .....	14
5.2.3 Handling and packaging of tested samples .....	15
5.3 Acceptance criteria .....	15
5.4 Quality assurance .....	16
5.4.1 Data .....	16
5.4.2 Nonconformance.....	16
5.4.3 Calibration.....	16
5.4.4 Traceability .....	16
<b>Annex A (normative) Test result sheet - DRD</b> .....	<b>17</b>
<b>Annex B (informative) Peel and pull-off test procedure</b> .....	<b>20</b>
<b>Annex C (informative) Fracture lines</b> .....	<b>22</b>

<b>Bibliography</b> .....	<b>23</b>
---------------------------	-----------

**Figures**

Figure 4-1 Test procedure flow diagram .....	9
Figure 5-1: Side view of the test fixtures .....	13
Figure A-1 : Example of test result sheet.....	19
Figure C-1 : Schematic cross-section of a coated substrate showing various fracture lines dependent on the weakest layer .....	22