

# ISO 7481:2023-11 (E)

## Aerospace - Nuts, self-locking, with maximum operating temperature less than or equal to 425 °C - Test methods

---

<b>Contents</b>		<b>Page</b>
Foreword.....		iv
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>1</b>
<b>4</b>	<b>Inspections and tests</b> .....	<b>1</b>
4.1	Hardness test.....	1
4.1.1	Procedure.....	1
4.1.2	Method.....	2
4.2	Bearing surface squareness test.....	2
4.2.1	Test device.....	2
4.2.2	Method.....	3
4.3	Axial load test.....	4
4.3.1	Test device.....	4
4.3.2	Method.....	4
4.4	Wrenching feature test.....	6
4.4.1	General.....	6
4.4.2	Test device.....	6
4.4.3	Method.....	7
4.5	Stress embrittlement test.....	7
4.5.1	General.....	7
4.5.2	Test device.....	7
4.5.3	Method.....	7
4.6	Torque-out test.....	8
4.6.1	General.....	8
4.6.2	Test device.....	9
4.6.3	Method.....	9
4.7	Test of no rotation of the captive washer.....	9
4.7.1	General.....	9
4.7.2	Test device.....	10
4.7.3	Method.....	10
4.8	Push-out test.....	10
4.8.1	General.....	10
4.8.2	Test device.....	10
4.8.3	Method.....	11
4.9	Self-locking torque at ambient temperature.....	12
4.9.1	Test device.....	12
4.9.2	Method.....	12
4.10	Self-locking torque at ambient temperature after heat soak at maximum operating temperature.....	14
4.10.1	Test device.....	14
4.10.2	Method.....	14
4.11	Permanent set test.....	15
4.11.1	General.....	15
4.11.2	Test device.....	15
4.11.3	Method.....	15
4.12	Vibration test.....	16
4.12.1	General.....	16
4.12.2	Test device.....	16
4.12.3	Method.....	18