

# ISO 8642:2025-07 (E)

## Aerospace - Self-locking nuts with maximum operating temperature greater than 425 °C - Test methods

---

Contents		Page
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Inspections and tests .....	1
4.1	Hardness test .....	1
4.1.1	Procedure .....	1
4.1.2	Method .....	2
4.2	Bearing surface squareness test .....	2
4.2.1	Test device .....	2
4.2.2	Method .....	3
4.3	Axial load test .....	4
4.3.1	Test device .....	4
4.3.2	Method .....	4
4.4	Wrenching feature test .....	5
4.4.1	General .....	5
4.4.2	Test device .....	5
4.4.3	Method .....	6
4.5	Torque-out test .....	6
4.5.1	General .....	6
4.5.2	Test device .....	7
4.5.3	Method .....	7
4.6	Test of no rotation of the captive washer .....	8
4.6.1	General .....	8
4.6.2	Test device .....	8
4.6.3	Method .....	8
4.7	Push-out test .....	8
4.7.1	General .....	8
4.7.2	Test device .....	9
4.7.3	Method .....	9
4.8	Self-locking torque at ambient temperature .....	10
4.8.1	Test device .....	10
4.8.2	Method .....	11
4.9	Self-locking torque at ambient temperature after heat soak at maximum operating temperature .....	12
4.9.1	Test device .....	12
4.9.2	Method .....	14
4.10	Permanent set test .....	15
4.10.1	General .....	15
4.10.2	Test device .....	15
4.10.3	Method .....	16
4.11	Vibration test .....	17
4.11.1	General .....	17
4.11.2	Test device .....	17
4.11.3	Method .....	19
4.12	Swaging test .....	20
4.12.1	General .....	20

<b>4.12.2 Visual examination .....</b>	<b>20</b>
<b>Bibliography .....</b>	<b>21</b>