

ISO 5858:2026-05 (E)

Aerospace - Nuts, self-locking, with maximum operating temperature less than or equal to 425 °C - Procurement specification

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Quality assurance	3
4.1	General	3
4.1.1	Manufacturer's approval	3
4.1.2	Qualification of nuts	3
4.1.3	Production acceptance of nuts	3
4.2	Qualification inspection and test conditions	3
4.3	Production acceptance inspection and test conditions	4
4.4	Use of statistical process control (SPC)	4
5	Technical requirements	5
Annex A (normative) Types of permissible surface discontinuity		28
Annex B (informative) Cross-sectional area formula		29
Bibliography		30